

ASS. REC. BY:

Sun Pin

REF:

CS/CT121002865/Qvd1.

Veron

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: Smm 3115KPolicy No. DMPCSN WDU141562000Claims No. Smm 21D20130/CO2

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLF66292 Yr Regn: 02/09/2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Sienta 1.5G C.C. 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 383748 T/Radio: Insured / Std / NI / NAEng/No: -C/No: NSP1707025751 *Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60 R15R: 185/60 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firenza

Front _____ Rear _____

R/Bal. 6 mm / R/Bal. 6 mmL/Bal. 6 mm / L/Bal. 6 mmD.O.A. 26/02/2021 D.O.I. 03/03/2021Survey held at LCRDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Mr: 55,000

Pr: 36,964

Nr: 18,036.

23/4/21 Final fig \$ 3217.50 confirmed by email (Recd 11,932.18, 789)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/4/21-Typist

Report Form: Merimen

Lump Sum / I.B.I. (\$) \$3217.50

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

ACCIDENT STATEMENT		LCR ARC
Date of Report	26-Feb-2021	
Date (DD/MM/YYYY) of Accident	26 Feb 2021	
Time (00:00hrs) of Accident	930	
Exact Location of Accident	TOA PAYOH LORONG 2	
Country / State of Loss	SINGAPORE	
DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SLF6629Z	
Insured / Policyholder		
Name of Registered Owner	LION CITY RENTALS PTE LTD	
Co Reg No	201504621K	
Email Address	rentals@lioncityrentals.com.sg	
Mobile No	-	
Alternative Phone No	6252 5525	
Vehicle Particulars	-	
Manufacturer		
Manufacturer	TOYOTA	
Model	SIENTA	
Exact purpose of which vehicle was being used at time of accident	PRIVATE HIRE / PRIVATE USAGE	
Are you claiming under your own insurance policy for repair to your vehicle	NO	
If no, Please state action to be taken	-	
Vehicle Category	PRIVATE CAR	
Insurance Company		
Name of Insurance Company	TOKYO MARINE INSURANCE SINGAPORE LTD	
Type of Insurance Coverage	THIRD PARTY	
Fleet Policy	YES	
Policy Number	20-ML00021-MM000076-R00-R00	
Cover Note Number	-	
Driver		
Main Hirer? (Select "No" if Ex-hirer)	Yes	
Name of Driver	LIU YUEN LIAN (3279Z)	
NRIC No	S6933279Z	
Date of Birth	21/9/1969	
Occupation	OUTDOOR	
Date of Driving passed	8/5/1991	
Gender	FEMALE	
Mobile number (LOCAL)	96486010	
Fax Number	-	
Contact Number	-	
Email Address	ANNLIUYUENLIAN@GMAIL.COM	
Address	631 SENJA ROAD #07-228 Singapore 670631	
Was the driver an employee of the insured's company?	NO	
If no, Relationship of the driver with the Insured	Hirer	
Vehicle Registration Number of Driver's Own vehicle	-	
Insurance Company Of Driver's Own Vehicle	-	
General Information of the Accident		
Type of Accident	COLLISION HEAD TO REAR	
Weather Condition	CLEAR	
Road Surface	DRY	
Other Information		
Was any foreign vehicle involved in this accident?	No	
Number of Vehicles (including own vehicle) involved in the accident	2	
Was any injured conveyed to the hospital by ambulance?	No	

ACCIDENT STATEMENT	LCR ARC
Was any other material or property damaged?	No
I have been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Number of Passangers (including driver)	2
Details of Police Action	
Was the accident reported to the police ?	No
If Yes, state the police station (If no, please indicate NA)	NA
Was notice of intended prosecution given?	No
If Yes, against who? (If no, please indicate NA)	NA
Circumstances of Accident	
Are accident photos available for attachment?	Yes
Was there any video captured by the car camera?	No
Was the audio recorded?	No
Insured Passanger Details	
Name of passanger 1 & Gender	Male
Name of passanger 2 & Gender	
Name of passanger 3 & Gender	
Name of passanger 4 & Gender	
Name of passanger 5 & Gender	
Name of passanger 6 & Gender	
Vehicle Registration Number	
SMM3115K	
Vehicle Category	
DETAILS OF OTHER VEHICLE PROPERTY 2	
Vehicle Registration Number	
Vehicle Category	
DETAILS OF OTHER VEHICLE PROPERTY 3	
Vehicle Registration Number	
Vehicle Category	
DETAILS OF OTHER VEHICLE PROPERTY 4	
Vehicle Registration Number	
Vehicle Category	
DETAILS OF OTHER VEHICLE PROPERTY 5	
Vehicle Registration Number	
Vehicle Category	
DETAILS OF WITNESS	
Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



SMM 3115 K

SLF66292

Describe Circumstances of the Accident

On 26 February 2021 at around 0930 hrs, I was driving my car (SLF6629Z) at Lor 2 Tea Poyoh towards PIE. While my car stationery at slip road waiting to exit to PIE, another vehicle (SMM3115K) hit the back of my car. There was one passenger in the car when accident happened.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd

Date: 27/02/2021

Attn : **MOTOR CLAIMS DEPT**

ESTIMATE

VEHICLE NO. SLF6629Z

CHASSIS NO : NSP1707025751

MAKE / MODEL : Toyota Sienta 1.5G A

DATE OF ACCIDENT : 26 Feb 2021

YOUR INSURED VEHICLE NUMBER :SMM3115K

MILEAGE : 383748 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate / CRU	1PC	\$ 1,470.00	\$ 1,470.00
4	Rear tailgate weatherstrip	1PC	\$ 360.00	\$ 360.00
5	Rear tailgate lock assy / Jam	1PC	\$ 504.00	\$ 504.00
6	Rear tailgate lock catch X	1PC	\$ 64.80	\$ 64.80
7	Rear tailgate RH upper hinge X	1PC	\$ 136.80	\$ 136.80
8	Rear tailgate LH upper hinge X	1PC	\$ 136.80	\$ 136.80
9	Rear tailgate LH damper X	1PC	\$ 352.80	\$ 352.80
10	Rear tailgate RH damper X	1PC	\$ 352.80	\$ 352.80
11	Rear tailgate back door inner trimboard X	1PC	\$ 580.00	\$ 580.00
12	Rear tray luggage compartment X	1PC	\$ 420.00	\$ 420.00
13	Rear spare tyre compartment box X	1PC	\$ 400.00	\$ 400.00
14	Rear spare tyre panel X	1PC	\$ 1,200.00	\$ 1,200.00
15	Rear tailgate center garnish holder / CRU	1PC	\$ 342.00	\$ 342.00
16	Rear tailgate Toyota logo / NEC	1PC	\$ 60.00	\$ 60.00
17	Rear licence lamp X	1PC	\$ 120.00	\$ 120.00
18	R/R taillamp X	1PC	\$ 550.00	\$ 550.00
19	R/L taillamp X	1PC	\$ 550.00	\$ 550.00
20	R/L tailgate reflector X	1PC	\$ 380.00	\$ 380.00
21	R/R tailgate reflector X	1PC	\$ 380.00	\$ 380.00
26	Rear end panel X R	1PC	\$ 828.00	\$ 828.00
27	Rear end panel lower X	1PC	\$ 633.60	\$ 633.60
28	Rear end panel top garnish X	1PC	\$ 250.00	\$ 250.00
32	Rear bumper cover / CRU	1PC	\$ 900.00	\$ 900.00
33	Rear bumper LH side bracket X	1PC	\$ 105.00	\$ 105.00
34	Rear bumper RH side bracket X	1PC	\$ 105.00	\$ 105.00
35	Rear bumper LH bracket X	1PC	\$ 90.00	\$ 90.00
36	Rear bumper RH bracket X	1PC	\$ 90.00	\$ 90.00
37	Rear bumper RH seal X	1PC	\$ 104.40	\$ 104.40
38	Rear bumper LH seal X	1PC	\$ 104.40	\$ 104.40
39	Rear bumper RH support X	1PC	\$ 88.05	\$ 88.05
40	Rear bumper LH support X	1PC	\$ 88.05	\$ 88.05
41	Rear bumper LH extension side pad X	1PC	\$ 216.00	\$ 216.00
42	Rear bumper RH extension side pad X	1PC	\$ 216.00	\$ 216.00

43	Rear bumper center black pad ✓ CNW	1PC	\$	288.00	\$	288.00
44	Rear bumper RH reflector ✗	1PC	\$	133.20	\$	133.20
45	Rear bumper RH reflector ✗	1PC	\$	133.20	\$	133.20
46	Rear bumper tow cover ✗	1PC	\$	40.00	\$	40.00
47	Keyless smart buzzer antenna ✗	1PC	\$	120.00	\$	120.00

LIST TOTAL S\$: \$ 12,892.90

25.00% DISCOUNT S\$: \$ 3,223.23
\$ 9,669.68

SPECIAL NETT

1	Rear Bumper clips ✓ NCC	1 SET	\$	80.00	30
2	Reverse sensor ✗	1 SET	\$	260.00	
3	Windscreen sealant ✗ / NCC	1PC	\$	100.00	30
4	Body sealant ✗	1PC	\$	100.00	✗
5	Rear number plate ✗	1PC	\$	100.00	✗

Special Nett Total S\$: \$ 640.00

LABOUR CHARGES

1	To remove and install rear tailgate glass	\$	120.00	✓
2	Transfer tailgate mechanism, upholstery, seats	\$	120.00	60
3	To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacemnt of damaged parts. Also include straightenning of both rear chassis members and floor panel.	\$	2,800.00	650
4	To respray rear tailgate, rear end panel,	\$	1,800.00	400

LABOUR TOTAL S\$: \$ 4,840.00

TOTAL S\$: \$ 15,149.68

7% GST \$ 1,060.48

GRAND TOTAL S\$: \$ 16,210.15

P/P

before paint photo

Sun Pin (LKK)

03/03/2021

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

vern

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms China Taiping Insurance (Singapore) Pte Ltd

Date: 27/02/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLF6629Z

CHASSIS NO : NSP1707025751

MAKE / MODEL : Toyota Sienta 1.5G A

DATE OF ACCIDENT : 26 Feb 2021

YOUR INSURED VEHICLE NUMBER :SMM3115K

MILEAGE : 383748 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear tailgate / CRW	1PC	\$ 1,470.00	\$ 1,470.00	1,180
4	Rear tailgate weatherstrip X SVC	1PC	\$ 360.00	\$ 360.00	X
5	Rear tailgate lock assy / Jam	1PC	\$ 504.00	\$ 504.00	317
6	Rear tailgate lock catch X SVC	1PC	\$ 64.80	\$ 64.80	X
7	Rear tailgate RH upper hinge X SVC	1PC	\$ 136.80	\$ 136.80	X
8	Rear tailgate LH upper hinge X SVC	1PC	\$ 136.80	\$ 136.80	X
9	Rear tailgate LH damper X SVC	1PC	\$ 352.80	\$ 352.80	X
10	Rear tailgate RH damper X SVC	1PC	\$ 352.80	\$ 352.80	X
11	Rear tailgate back door inner trimboard X SVC	1PC	\$ 580.00	\$ 580.00	X
12	Rear tray luggage compartment X SVC	1PC	\$ 420.00	\$ 420.00	X
13	Rear spare tyre compartment box X SVC	1PC	\$ 400.00	\$ 400.00	X
14	Rear spare tyre panel X SVC	1PC	\$ 1,200.00	\$ 1,200.00	X
15	Rear tailgate center garnish holder / CRW	1PC	\$ 342.00	\$ 342.00	207
16	Rear tailgate Toyota logo / NEC	1PC	\$ 60.00	\$ 60.00	/
17	Rear licence lamp X SVC	1PC	\$ 120.00	\$ 120.00	X
18	R/R taillamp X SVC	1PC	\$ 550.00	\$ 550.00	X
19	R/L taillamp X SVC	1PC	\$ 550.00	\$ 550.00	X
20	R/L tailgate reflector X SVC	1PC	\$ 380.00	\$ 380.00	X
21	R/R tailgate reflector X SVC	1PC	\$ 380.00	\$ 380.00	X
26	Rear end panel X R	1PC	\$ 828.00	\$ 828.00	X
27	Rear end panel lower X SVC	1PC	\$ 633.60	\$ 633.60	X
28	Rear end panel top garnish X SVC	1PC	\$ 250.00	\$ 250.00	X
32	Rear bumper cover / CRW	1PC	\$ 900.00	\$ 900.00	517
33	Rear bumper LH side bracket X SVC	1PC	\$ 105.00	\$ 105.00	X
34	Rear bumper RH side bracket X SVC	1PC	\$ 105.00	\$ 105.00	X
35	Rear bumper LH bracket X SVC	1PC	\$ 90.00	\$ 90.00	X
36	Rear bumper RH bracket X SVC	1PC	\$ 90.00	\$ 90.00	X
37	Rear bumper RH seal X SVC	1PC	\$ 104.40	\$ 104.40	X
38	Rear bumper LH seal X SVC	1PC	\$ 104.40	\$ 104.40	X
39	Rear bumper RH support X SVC	1PC	\$ 88.05	\$ 88.05	X
40	Rear bumper LH support X SVC	1PC	\$ 88.05	\$ 88.05	X
41	Rear bumper LH extension side pad X SVC	1PC	\$ 216.00	\$ 216.00	X
42	Rear bumper RH extension side pad X SVC	1PC	\$ 216.00	\$ 216.00	X

43	Rear bumper center black pad	✓ CNU	1PC	\$ 288.00	\$ 288.00	209
44	Rear bumper RH reflector	✗ Svc	1PC	\$ 133.20	\$ 133.20	✗
45	Rear bumper RH reflector	✗ Svc	1PC	\$ 133.20	\$ 133.20	✗
46	Rear bumper tow cover	✗ Svc	1PC	\$ 40.00	\$ 40.00	✗
47	Keyless smart buzzer antenna	✗ Svc	1PC	\$ 120.00	\$ 120.00	✗

LIST TOTAL S\$: \$ 12,892.90 2,490
 25.00% DISCOUNT S\$: \$ 3,223.23 -25%
 \$ 9,669.68 1,867.50

SPECIAL NETT

1	Rear Bumper clips	✓ NUC	1 SET	\$ 80.00	30
2	Reverse sensor	✗ Svc	1 SET	\$ 260.00	✗
3	Windscreen sealant	✗ NUC	1PC	\$ 100.00	40
4	Body sealant	✗ Svc	1PC	\$ 100.00	✗
5	Rear number plate	✗ Svc	1PC	\$ 100.00	✗
Special Nett Total S\$:				\$ 640.00	70

LABOUR CHARGES

1	To remove and install rear tailgate glass	\$ 120.00	✓
2	Transfer tailgate mechanism, upholstery, seats	\$ 120.00	60
3	To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts. Also include straightening of both rear chassis members and floor panel.	\$ 2,800.00	650
4	To respray rear tailgate, rear end panel,	\$ 1,800.00	450

LABOUR TOTAL S\$: \$ 4,840.00
 TOTAL S\$: \$ 15,149.68
 7% GST \$ 1,060.48
 GRAND TOTAL S\$: \$ 16,210.15

PAP
 before paint photo

Sun Pin(LKK)

03/03/2021

TP without prejudice

1,867.50
 70
 1,280
 3,217.50

P/P
 \$ 3,217.50

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: