

PREMIUM AUTOMOBILES

55 UBI ROAD 1 SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam

Veron.

Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EA 2318 G

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defect</i>	1	\$ 1,787.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 587.00	+
3	FRONT BUMPER SECURING STRIP <i>new</i>	21	\$ 36.00	✓
4	FRONT BUMPER CLOSING ELEMENT LOWER CTR <i>new</i>	1	\$ 210.00	+
5	FRONT BUMPER AIR GUIDE RH <i>Defect</i>	1	\$ 63.00	✓
6	FRONT BUMPER AIR GUIDE GRILLE RH <i>new</i>	1	\$ 365.00	+
7	FRONT BUMPER GUIDE SECTION RH <i>Defect</i>	1	\$ 38.00	✓
8	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 124.00	+
9	FRONT BUMPER CARRIER <i>new</i>	1	\$ 845.00	+
10	FRONT BUMPER COVER <i>new</i>	1	\$ 127.00	+
11	CAUTION STICKER LABEL <i>new</i>	1	\$ 14.00	+
12	AIRCON STICKER LABEL <i>new</i>	1	\$ 8.00	+
13	FRONT LOCK CARRIER BRACKET <i>new</i>	1	\$ 137.00	+
14	FRONT BUMPER SUPPORT BRACKET LH / RH <i>new</i>	2	\$ 58.00	+
15	LOW TONE FANFARE RH <i>new</i>	1	\$ 126.00	+
16	SPRING SHACKLE RH <i>new</i>	1	\$ 29.00	+
17	FRONT PARKING AID SENSOR INNER / OUTER <i>new</i>	2	\$ 244.00	+
18	FRONT PARKING SENSOR SEAL RING <i>new</i>	4	\$ 14.00	+
19	FRONT FENDER RH <i>Defect</i>	1	\$ 767.00	✓
20	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 202.00	+
SUB TOTAL SPARE PARTS		:	\$ 5,781.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.HAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. EA 2318 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER END PLATE RH <i>Dmgd</i>	1	\$ 72.00	✓
22	FRONT FENDER BRACKET RH ?	1	\$ 35.00	?
23	FRONT FENDER CENTRE BRACKET RH ?	1	\$ 49.00	?
24	FRONT FENDER POP RIVET ?	6	\$ 20.00	?
25	FRONT FENDER BRACKET RH ?	1	\$ 32.00	?
26	FRONT FENDER BRACE RH <i>Best</i>	1	\$ 118.00	✓
27	FRONT FENDER WHEEL HOUSING LINER RH <i>cracked</i>	1	\$ 241.00	✓
28	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 233.00	+
29	FRONT WHEEL SPOILER RH <i>from</i>	1	\$ 73.00	✓
30	FRONT WHEEL SPOILER TRIM RH ?	1	\$ 36.00	?
31	FRONT FENDER STONE CHIP GUARD <i>new</i>	1	\$ 51.00	+
32	FRONT FENDER LEDGE COVER RH LONG ?	1	\$ 31.00	?
33	FRONT FENDER LEDGE COVER RH SHORT <i>Dmgd</i>	1	\$ 23.00	✓
34	LED HEADLIGHT RH <i>cut</i>	1	\$ 7,693.00	✓
35	HEADLIGHT LIFT CYLINDER RH ?	1	\$ 210.00	?
36	HEADLIGHT WASHER HOSE	1	\$ 93.00	+
37	RADIATOR AIR GUIDE RH BIG	1	\$ 28.00	+
38	RADIATOR AIR GUIDE RH SMALL	1	\$ 12.00	+
39	ALUMINIUM RIM RH FRONT <i>new</i>	1	\$ 1,142.00	+
40	SUNDRIES ?	1	\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 16,223.00	
TOTAL LABOUR CHARGES		:	\$ 5,401.00	
GRAND TOTAL		:	\$ 21,624.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

N 016 185 7 X 6

WHT 006 772 A X 2

*Revised Amount
22/03/21
H.S.*