

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMP4842Y (Insd veh)	Model:	TOYOTA HIACE 2.8 D
	PC8125R (TP veh)		COMMUTER GL (A)
Date of Accident:	26/02/2021		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	4,720.22	
Final Repair Cost	: \$	963.00	
Loss of Use	: \$	200.00	2.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	1,170.45	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u>:		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u>:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hui Yang Motor Pte Ltd	: \$	1,170.45
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

30 Mar
2021

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))