

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0050/2021
DATE : 23-MAR-2021

ERGO INSURANCE PTE LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
S(038988)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : THAI KIAN LYE
ADDRESS : APT BLK 602 ELIAS ROAD
#13-238
S(510602)
TELEPHONE NO : 96664528

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800137470-02
VEHICLE NO : SBW54A
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YE50257
CHASSIS NO : JF1SJ5KC5JG112545
MILEAGE : 55227 KM
DATE IN : 23/03/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 02/03/2021

Print Date : 30/04/2021
Print Time : 11:54:59

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBW54A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST GBJ4229E - ERGO INSURED		
2	ZZ/001	CONDUCT TP CLAIM ERGO DATE:02/03/2021 TIME:1925HRS LOCATION:BEDOK SOUTH ROAD		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER, TAILGATE, BEAM & PANEL	1120.00	1120.00
4	ZZ/003	RESPRAY REAR BUMPER, TAILGATE, BEAM & PANEL	840.00	840.00
5	ZZ/004	TRANSFER TAILGATE MECHANISM	150.00	150.00
6	ZZ/005	REMOVE & REFLX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS	150.00	150.00
7	ZZ/006	REMOVE & INSTALL REAR WINDSCREEN	300.00	300.00
8	ZZ/007	TO CONDUCT REAR LIGHTING TEST	30.00	30.00
9	ZZ/008	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	145.00	145.00
10	ZZ/009	SUNDRIES	20.00	20.00
		TOTAL LABOUR CHARGES	2755.00	2755.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBW54A

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE REAR FORESTER IL (SUPP)	57704SG012	540.00			OK
2	BRKT CORNER R LH	57707SG070	18.00			OK
3	BRKT SD R LH	57707SG090	14.40			OK
4	COVER HOOK R	57731SG010NN	12.60			OK
5	COVER BMPR R (EXHAUST)	57731SG060	14.40			OK
6	PANEL CPL R/G NA	60809SG0109P	1072.80			OK
7	GLASS R/G	63019SG000	799.20			OK
8	RUBBER DAM GLS	63232SG000	7.20			OK
9	RUBBER R/G	63232SG010	12.60			OK
10	LETTER MARK FORESTOR R (SUPP)	93079SG000	39.60			OK
11	LETTER MK R SUB (SUPP)	93079SG030	64.80			OK
SUB TOTAL			2595.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			519.12	0.00	0.00	0.00
GRAND TOTAL			2076.48	0.00	0.00	0.00
OVERALL TOTAL			2076.48			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SBW54A

NETT ITEM 2595.60
LESS 20 % -519.12
NETT AMOUNT 2076.48

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 2755.00
TOTAL SPARE PARTS CHARGES 2076.48

TOTAL CHARGES 4831.48
ADD 7 % GST 338.20

GRAND TOTAL 5169.68
