

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: MC/MC 11186/2020 Date: 19<sup>th</sup> March 2021

Our Ref: CS1/LAW21002921/Aqd3e2

## M/s C. Yogarajah LLC 883 North Bridge Road #19-05 Southbank Singapore 198785

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJA 5535S INSURED VEHICLE: SCZ 6900R

ACCIDENT DATE: 17/05/2016

We thank you for your instruction on 02/03/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJA 5535S from M/s Par Automotive Consultancy.
- b) Final Repair Bill of SJA 5535S from M/s Twincar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJA 5535S and SCZ 6900R.
- d) Colour damaged vehicle photographs of SJA 5535S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJA 5535S

Make & Model : Subaru 2.5WRX STI Chassis Number : JF1GDFKH37G065335

Year of Registration : 2007 Engine Capacity : 2457 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.