

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0188/2021/HR
DATE : 4-Mar-21
WIP : 17934

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 4/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS DHARMARAJ MELANCIA SNEGA LATHA
ADDRESS : 31 BEDOK SOUTH AVENUE 2
#19-307
SINGAPORE 460031
TELEPHONE : HP +65 90625461
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900090599-02
VEHICLE NO : **SMH 7690 R**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 30/1/2019
ENGINE NO : CVK 075880
CHASSIS NO : WAUZZZF43KA029160
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Mar-21
PLACE OF ACCIDENT : NEAR BEDOK S RD, OPP BLOCK 367
SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE NO. SMH 7690 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,200.00	
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	
5	TO RESPRAY FRONT BUMPER, BONNET AND LHS FRONT FENDER.	\$	2,900.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$	10,722.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7690 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,787.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 587.00	
3	FRONT BUMPER SECURING STRIP	1	\$ 36.00	
4	FRONT BUMPER CENTRE GRILLE	1	\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT LOWER CTR	1	\$ 210.00	
6	FRONT BUMPER AIR GUIDE LH	1	\$ 63.00	
7	FRONT BUMPER RADIATOR GRILLE	1	\$ 1,332.00	
8	FRONT BUMPER AIR GUIDE GRILLE RH	1	\$ 135.00	
9	FRONT BUMPER CARRIER	1	\$ 845.00	
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 124.00	
11	FRONT BUMPER TOP COVER	1	\$ 127.00	
12	FRONT BUMPER GUIDE SECTION LH	1	\$ 36.00	
13	FRONT BUMPER GUIDE SECTION BRACKET LH	1	\$ 228.00	
14	FRONT LOCK CARRIER BRACKET	1	\$ 137.00	
15	FRONT BUMPER SUPPORT BRACKET LH / RH	2	\$ 58.00	
16	CAUTION STICKER LABEL	1	\$ 14.00	
17	AIRCON STICKER LABEL	1	\$ 8.00	
18	FRONT PARKING AID SENSOR INNER / OUTER	2	\$ 244.00	
19	FRONT PARKING SENSOR SEAL RING	4	\$ 14.00	
20	HIGH TONE HORN LH	1	\$ 126.00	
SUB TOTAL SPARE PARTS		:	\$ 6,307.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7690 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HIGH TONE HORN SPRING SHACKLE LH	1	\$ 29.00	
22	FRONT FENDER LH	1	\$ 767.00	
23	FRONT FENDER ATTACHMENT PARTS	1	\$ 202.00	
24	FRONT BUMPER CLOSING ELEMENT LH	1	\$ 72.00	
25	FRONT BUMPER BRACKET LH	1	\$ 35.00	
26	FRONT BUMPER BRACKET LH	1	\$ 49.00	
27	FRONT BUMPER BRACE LH	1	\$ 118.00	
28	FRONT WHEEL HOUSING LINER	1	\$ 240.00	
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 233.00	
30	FRONT FENDER WHEEL SPOILER	1	\$ 73.00	
31	FRONT FENDER END PLATE LH	1	\$ 35.00	
32	FRONT FENDER STONE CHIP GUARD LH	1	\$ 51.00	
33	FRONT FENDER OUTER LEDGE COVER	1	\$ 31.00	
34	FRONT FENDER INNER LEDGE COVER	2	\$ 23.00	
35	FRONT FENDER IMPACT PROTECTION LH / RH / CTR	3	\$ 84.00	
36	LED HEADLIGHT	1	\$ 7,693.00	
37	CONTROL MODULE FOR MAIN LIGHT SYSTEM	2	\$ 761.00	
38	CONTROL MODULE FOR LIGHT CONTROL SYSTEM	4	\$ 751.00	
39	HEADLIGHT DRAIN HOSE	1	\$ 36.00	
40	HEADLIGHT LIFT CYLINDER LH	1	\$ 210.00	
SUB TOTAL SPARE PARTS		:	\$ 11,493.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7690 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	HEADLIGHT LIFT CYCLINDER BRACKET LH	1	\$ 6.00	
42	HEADLIGHT WASHER HOSE	6	\$ 93.00	
43	RADIATOR CARRIER	1	\$ 1,016.00	
44	RADIATOR SUPPORT BRACKET	1	\$ 38.00	
45	COOLANT	1	\$ 179.00	
46	RADIATOR OUTER DUCT	1	\$ 28.00	
47	RADIATOR INNER DUCT	1	\$ 12.00	
48	RADIATOR AIR GUIDE UPPER / LOWER	2	\$ 38.00	
49	FRONT NUMBER PLATE	1	\$ 60.00	
50	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS			\$ 19,570.00	
TOTAL LABOUR CHARGES			\$ 10,722.00	
GRAND TOTAL			\$ 30,292.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT