

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2021)
 Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHA9537J/02/03/2021 10:56
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	des *458.60 FL
2	1		*REAR BUMPER CENTRE GUARD	20.00	0.00	de *552.60 FL
3	10		*REAR BUMPER CLIPS	20.00	0.00	ner *22.00 FL
4	1		*REAR BUMPER MAT	0.00	0.00	ne *50.00 F
5	1		*REVERSE SENSOR	0.00	0.00	ant *135.70 F
Sub Total (\$)						1,218.90
- List Item Discount on L Items (\$)						206.64
Total Parts (\$)						1,012.26

ComfortDelGro Engineering Pte Ltd/SHA9537J/02/03/2021 10:56. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

1352
 25% 7014
 3N - 185.70

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	1 OD/TP Case (Insurer)	11.00
Sub Total (S\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 400.00
2	SPARYPAINT	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	30 80.00
Gross Labour Cost (S\$)			630 780.00

ComfortDelGro Engineering Pte Ltd/SHA9537J/02/03/2021 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphir 97495745
WP 3/3/21 @ 5pm

• 2 days 4/5 Resurvey after repair
tanphir @ hkanato.com

Wstahn - 1845.70
4581450
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: