

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0189/2021/HR
DATE : 4-Mar-21
WIP : 18028

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM LEASING PTE LTD
ADDRESS : 9 LENG KEE ROAD
SINGAPORE 159090
TELEPHONE : HP +65 98738993
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 999993757/100875440-00000
VEHICLE NO : **SML 447 C**
MODEL CODE : Q2 1.0 TFSI S TRONIC
MODEL YEAR : 30/4/2019
ENGINE NO : CHZ C29359
CHASSIS NO : WAUZZZGA4KA050703
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Mar-21
PLACE OF ACCIDENT : 1 KIM SENG PROMENADE. B2 CARPARK.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 447 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	X
2	TO RENEW LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$ 300.00	X
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$ 400.00	X
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	\$ 280.00	X
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	\$ 1,400.00	X
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	\$ 1,400.00	X
SUB LABOUR CHARGES		\$ 4,060.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 447 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES
7	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N \$ 280.00 *
8	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00 350.
9	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,800.00 1750.
10	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS SILL PANEL, LHS C-PILLAR TRIM, LHS REAR DOOR, DOOR HANDLE, LHS FRONT DOOR, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCE AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	\$ 7,400.00 1750 3 x 550 = 1650 Handle : 100 1750
11	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		\$ 19,412.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 447 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER COVER UPPER <i>Regr</i>	1	\$ 1,280.00	X	
2	REAR BUMPER FIXING PARTS	1	\$ 77.00	X	
3	REAR BUMPER SPOILER	1	\$ 284.00	X	
4	REAR LIGHT REFLECTOR LH	1	\$ 30.00	+	
5	REAR BUMPER GUIDE SECTION LH	1	\$ 53.00	X	
6	REAR SIDE PANEL <i>Regr</i>	1	\$ 2,359.00	X	
7	REAR DOOR WINDOW LH	1	\$ 314.00	+	
8	PRIMER	1	\$ 20.00	+	
9	REAR WHEEL COVER LH / RH <i>Regr</i>	2	\$ 340.00	X	
10	REAR DOOR LH <i>Distorted</i>	1	\$ 2,756.00	✓	
11	REAR DOOR OUTER DOOR SEAL <i>Regr</i>	1	\$ 135.00	✓	
12	BONDING AGENT ?	1	\$ 49.00	?	
13	CLEANING SOLUTION ?	1	\$ 68.00	?	
14	APPLICATOR ?	1	\$ 8.00	?	
15	REAR DOOR ATTACHMENT PARTS <i>Regr</i>	1	\$ 94.00	X	
16	REAR DOOR CATCH	1	\$ 120.00	?	
17	REAR DOOR SEAL INNER / OUTER <i>Regr</i>	2	\$ 341.00	X	
18	REAR DOOR LOWER COVER LH <i>ht</i>	1	\$ 226.00	✓	
19	REAR DOOR HANDLE LH <i>Regr</i>	1	\$ 374.00	X	
20	REAR DOOR HANDLE CAP LH <i>Regr</i>	1	\$ 52.00	X	
SUB TOTAL SPARE PARTS		:	\$ 8,980.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 447 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR SLIDE VALVE	1	\$ 22.00	X
22	REAR DOOR MOUNTING BAR	1	\$ 162.00	X
23	BOWDEN CABLE	1	\$ 52.00	X
24	REAR DOOR WINDOW REGULATOR LH	1	\$ 282.00	X
25	REAR DOOR WINDOW REGULATOR MOTOR LH	2	\$ 295.00	X
26	REAR DOOR LOWER COVER LH	1	\$ 256.00	X
27	REAR DOOR TRIM PILLAR - LH	1	\$ 616.00	X
28	REAR WHEEL HOUSING LINER LH	1	\$ 203.00	X
29	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 57.00	X
30	REAR ALUMINIUM RIM LH	1	\$ 949.00	?
31	REAR DOOR SIDE SKIRT TRIM	1	\$ 280.00	X
32	FOAM STRIPS	1	\$ 138.00	X
33	PLASTIC PRIMER	1	\$ 106.00	X
34	1/4 GLASS SEALANT	S/N	\$ 100.00	X
35	ACRYLIC SEALANT	S/N	\$ 180.00	X
36	CAVITY WAX	S/N	\$ 140.00	X
37	STONE CHIP	S/N	\$ 180.00	X
38	METAL FILLER POWDER	S/N	\$ 280.00	X
39	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 13,578.00	
TOTAL LABOUR CHARGES		:	\$ 4,060.00	19412
GRAND TOTAL		:	\$ 17,638.00	32990

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6365 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Ling -
05/03/21

not Authorised, 06 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT