

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0189/2021/HR
DATE : 04-Mar-21
WIP : 18028

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

6 days - ok - Jy - 14 Apr 21

OWNER'S NAME : M/S PREMIUM LEASING PTE LTD
ADDRESS : 9 LENG KEE ROAD
SINGAPORE 159090
TELEPHONE : HP +65 98738993
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 999993757/100875440-00000
VEHICLE NO : **SML 447 C**
MODEL CODE : Q2 1.0 TFSI S TRONIC
MODEL YEAR : 30/04/2019
ENGINE NO : CHZ C29359
CHASSIS NO : WAUZZZGA4KA050703
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 01-Mar-21
PLACE OF ACCIDENT : 1 KIM SENG PROMENADE. B2 CARPARK.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 447 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	
2	TO RENEW LHS 1/4 GLASS TO FACILLITATE FENDER RENEWAL.	S/N \$ 300.00	
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$ 400.00	
4	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	\$ 280.00	
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	\$ 1,400.00	
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	\$ 1,400.00	
SUB LABOUR CHARGES		: \$ 4,060.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 447 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSSY.	S/N \$	280.00		
8	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$	350.00
9	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS FRONT DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,800.00	\$	1,750.00
10	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS SILL PANEL, LHS C-PILLAR TRIM, LHS REAR DOOR, DOOR HANDLE, LHS FRONT DOOR, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCE AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS.	\$	7,400.00	\$	1,750.00
11	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
12	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 19,412.00	\$	4,322.00

#####

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 447 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER COVER UPPER	1	\$ 1,280.00	
2	REAR BUMPER FIXING PARTS	1	\$ 77.00	
3	REAR BUMPER SPOILER	1	\$ 284.00	
4	REAR LIGHT REFLECTOR LH	1	\$ 30.00	
5	REAR BUMPER GUIDE SECTION LH	1	\$ 53.00	
6	REAR SIDE PANEL	1	\$ 2,359.00	
7	REAR DOOR WINDOW LH	1	\$ 314.00	
8	PRIMER	1	\$ 20.00	
9	REAR WHEEL COVER LH / RH	2	\$ 340.00	\$ 272.00
10	REAR DOOR LH	1	\$ 2,756.00	\$ 2,204.80
11	REAR DOOR OUTER DOOR SEAL	1	\$ 135.00	\$ 108.00
12	BONDING AGENT	1	\$ 49.00	
13	CLEANING SOLUTION	1	\$ 68.00	
14	APPILICATOR	1	\$ 8.00	
15	REAR DOOR ATTACHMENT PARTS	1	\$ 94.00	
16	REAR DOOR CATCH	1	\$ 120.00	
17	REAR DOOR SEAL INNER / OUTER	2	\$ 341.00	
18	REAR DOOR LOWER COVER LH	1	\$ 226.00	\$ 180.40
19	REAR DOOR HANDLE LH	1	\$ 374.00	
20	REAR DOOR HANDLE CAP LH	1	\$ 52.00	
SUB TOTAL SPARE PARTS		:	\$ 8,980.00	\$ 2,765.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 447 C

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
					\$	2,765.20
21	REAR DOOR SLIDE VALVE	1	\$ 22.00			
22	REAR DOOR MOUNTING BAR	1	\$ 162.00			
23	BOWDEN CABLE	1	\$ 52.00			
24	REAR DOOR WINDOW REGULATOR LH	1	\$ 282.00			
25	REAR DOOR WINDOW REGULATOR MOTOR LH	2	\$ 295.00			
26	REAR DOOR LOWER COVER LH	1	\$ 256.00			
27	REAR DOOR TRIM PILLAR - LH	1	\$ 616.00			
28	REAR WHEEL HOUSING LINER LH	1	\$ 203.00			
29	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 57.00			
30	REAR ALUMINIUM RIM LH	1	\$ 949.00			
31	REAR DOOR SIDE SKIRT TRIM	1	\$ 280.00			
32	FOAM STRIPS	1	\$ 138.00			
33	PLASTIC PRIMER	1	\$ 106.00			
34	1/4 GLASS SEALANT	S/N	\$ 100.00			
35	ACRYLIC SEALANT	S/N	\$ 180.00			
36	CAVITY WAX	S/N	\$ 140.00			
37	STONE CHIP	S/N	\$ 180.00			
38	METAL FILLER POWDER	S/N	\$ 280.00			
39	SUNDRIES		\$ 300.00		\$	2.56
TOTAL SPARE PARTS		:	\$ 13,578.00		\$	2,767.76
TOTAL LABOUR CHARGES		:	\$ 4,060.00		\$	4,322.00
GRAND TOTAL		:	\$ 17,638.00		\$	7,089.76

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT