

12/12/2020

REF: CS3/MSG20013871/Gqd3-1 Special Instruction:

ASS. REC. BY:

SURVEYOR: GQ

ASSIGNMENT (Office)

From (Person): KATHERINE WONG of MSIG

Date/Time: 8/3/2021 12:28 PM

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMW 4306S

Insured: SMP 333B

at Workshop m/s

BIFROST AUTO

Tel: 9329 0237

of 8 Kaki Bukit Ave 4 #01-49 PREMIER

Policy No: 1001534569

Claim No: 250901

Sum Insured:

Excess:

D.O.A. 12/12/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 4.32PM@15/12/20 Person Contacted: IKHWAN

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate	Repairer agreed to survey on 16/12/2020
	SMW 4306S-X	
	SMP 333B-NBA/INC20005399/Y	DOA : 24/04/2020