



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03 SINGAPORE LAND
TOWER SINGAPORE 048623

Ref: CS3/SMO21003032/Utd3e2

Date: 11/03/2021

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLM 3239Z	Veh. Inspected	SJZ 233P
Policy No.	D20MTPV01008884	Coverage (\$)	0.00
Claim No.	CMTD2100698/LOR	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	08/03/2021


2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2050402R159842	Colour	GREY
Odometer	80380 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	---

5. General Information

Accident Date	04/03/2021	Inspect Date / Time	08/03/2021 (03:29 PM)
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------

Report Ref No. CS3/SMO21003032/Utd3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.