



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL	INV No.	AC2101561
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER	INV Date	11/03/2021
SINGAPORE 048623	Reference	CS3/SMO21003032/Utd3e2
	Code	SMO

### PROFESSIONAL SERVICE FEE

Vehicle No.	SJZ 233P
Insured Veh.	SLM 3239Z
Claim No.	CMTD2100698/LOR
Policy No.	D20MTPV01008884
Accident Date	04/03/2021
Inspection Date	08/03/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 09.03.2021)	60.00
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**