ASS. REC. BY: CANT MEF: (S/11/2/003	23/10/1/23
The state of the s	SUMENT COEXPIRM: 2630 MM
Estimated Cost: ODITPIWSITP RESIDD RESIEVA/INVINV To Inspect Vehicle No: SDW 28172 at Workshop m/s J'S GARAGE	Veh No: SJW28172 Yr Regn: 7010 1 MAR. Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or Make: Volkswayen Solf R. 2-01: c.c. 1984 Colour BUE A/C: Insured / Std / NI / NA
of 48, Tett hum RD 5187 \$\frac{108}{108}\$ Insured: 111 Policy No. D20 MPC 000 4809 Claims No. MPC 2021 D00009 244 Sum Insured: Excess: 450 (Cilent's Record) Make of Veh:	Sp.Reading 6066 T/Radlo: Insured / Std / NI / NA Eng/No: C/No: WV W 222 IKZAW 242926 Gen. Cond: Good / Faly / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: NII / S/Rim / STD A/Rim or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date: Person Contacted: Date / Time Action / Instruction Paper Market Value: N/S O/S N/S	Tyre Size: F: 235/402618 R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO(YOKO or . Fron! Rear R/Bal. D.O.A. 28/02/21 Survey held at Des. of Damages: Frt./ Rear / O/S / N/S / U/C / Rooftop or
5H) IS 9400 Confirmed by e	(Red 12,166.80, 56%)
Dale/Time, File Pass to? : Prefit. Report : Final Report 2) 8/4/21-Typist Add Report Formal: Merimen Lucup Sum / I.S. ft. (S. LS \$9400	Days Of Repair: Resurvey No. of Trip: 1 Survey Fee: Transportation: S+RSSI Interview (\$) Photos Total Total

SV0K21320004 / VICOM LTD (VAC) - Bukit Batok [659545] ENTRY DATE & TIME: 02/03/2021 16:21 (SGT) SUBMITTED BY: Somanathan Thangavelloo VERSION: 1 (02/03/2021 16:21 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate. policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this norm by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

02/03/2021 16:21 (SGT) Date of Submission 28/02/2021 14:00 (SGT) Date of Accident **Exact Location of Accident** Singapore

CLEMENTI AVENUE 6 TOWRDS AYE /CTE Additional Location Information

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

SJW2811Z Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? No

KUNA SHEKARAN S/O RAMASAMY Name Of Registered Owner

SXXXX384B NRIC No

Email Address CTR2424@HOTMAIL.COM Mobile Phone No (Phone) +65-97878734

(Home) +65-97878734 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Volkswagen

Golf Model Variant

Exact purpose for which vehicle was being used at time of

Private use Are you claiming under your own insurance policy for repair to

Yes your vehicle?

Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company India International Type of Coverage Comprehensive

Fleet Policy D20MPC0004809 (COMP) Policy Number

Cover Note Number

DRIVER

RAKESH S/O KUNA SHEKARAN Name of Driver NRIC No SXXXX340E

25/05/1991 Date Of Birth Occupation Outdoor

Date Of Driving Pass Driving experience

Gender Mobile Number Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder? If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Head to Rear

15/09/2009

Male

650169

No

No

Child

11 YEARS AND 5 MONTHS

CTR2424@HOTMAIL.COM

APT BLK 169 BUKIT BATOK WEST AVENUE 8 #06-383

(Phone) +65-91998084

Clear Dry

No

No

Yes

2

No

2

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

PASSENGER 1

Name Gender

WIFE Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT ATTACH

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes No No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver NRIC No

SLU7473U

Private car TAI KAU SXXXX323J

Accident report SV0K21320004

Page 2 of 18

Contact Number		-
Address		$(\overline{\mathcal{T}})$
Address complement		
Postcode		-
nsurance Company Name		
Nature Of Damage		+
Details of property damaged in accident		-
No. Of Passenger (Including Driver)		-

		1 6
ON 23/02/2021 I	WAS DRIVING MY CAR ENTERING	AVE ICTE FROM CLEMENTI
AVE 6 AT TIME ARE	UNA MOOHAS , ONCE ENTERING AYE	THE FRONT CAR CITROEN CO
SLU74730 SUDDEN	LY JAM BRATE CAUSING ME TO H	HT HIS REAR OF THE CAR
eclaration		
We declare the foregoing particular	s are true in every respect.	
	7	
olicyholder's Signature / Date &	Driver's Signature (if driver is not the policyholder) / Do	ate Witnessed by Reporting Centre

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquines by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (a) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law, firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Driver's Signature (if driver is not the policyholder) / Date Witnessed by Reporting Centre Personnel

Time

Sketch Plan

A - SJW28112 B - SLV7473U





























PTE LTD

Address:

48 Toh Guan Road East, ENTERPRISE HUB

#02-108 SINGAPORE 608586

Hp: +65 96648646

Email: js.garage@me.com

Facebook: J's Garage Pte Ltd

Your Reference:

Please Advise

Our Reference:

SJW2811Z

Date:

22-May-18

Date of Accident:

19-May-18

Estimate:

JS/ 2021/ ETI009

Vehicle No:

SJW2811Z

Make:

VOLKSWAGEN

Model:

GOLF

No.	Job/ Parts Description	Qty/Ltr	Unit Price	Amount	Remarks
1	FRONT BUMPER CTA	1	\$968.00	\$968.00	
2	FRONT BUMPER UPPER SPOILER X SVL	1	\$222.00	\$222.00	X
3	FRONT BUMPER LOWER SPOILER 7. 49VC	1	\$671.00	\$671.00	X
4	FRONT BUMPER RH RETAINER ? CM/	1	\$72.60	\$72.60	
5	FRONT BUMPER LH RETAINER ? CM	1	\$72.60	\$72.60	
6	HEADLAMP LOWER BRACKET LH ? cm/	1	\$129.80	\$129.80	
7	HEADLAMP LOWER BRACKET RH ? CM/	1	\$129.80	\$129.80	
8	BUMPER LOWER GRILLE ? YSVE	1	\$690.00	\$690.00	X
9	FRONT GRILLE CA	1	\$472.00	\$472.00	
10	LAMP GRILLE LH ? X SVL	1	\$175.00	\$175.00	\star
11	LAMP GRILLE RH ? + SVC	1	\$175.00	\$175.00	+
12	LAMP GRILLE PLATE LH ? YSVC	1	\$45.00	\$45.00	X
13	LAMP GRILLE PLATE RH ? KIN	1	\$45.00	\$45.00	*
14	HEADLAMP LH CM/	1	\$1,850.00	\$1,850.00	
15	HEADLAMPRH CA/	1	\$1,850.00	\$1,850.00	
16	LED DAYLIGHT LH X SVC	1	\$682.00	\$682.00	X
17	LED DAYLIGHT RH X SV	1	\$682.00	\$682.00	+
18	BONNET 64/	1	\$858.00	\$858.00	
19	BONNET UNDERTRAY HEATSHIELD X500	1	\$120.00	\$120.00	X
20	BONNET HINGE LH X Suc	1	\$80.00	\$80.00	X
21	BONNET HINGE RH X SUC	1	\$80.00	\$80.00	*
22	SUPPORT CARRIER ?cm/	1	\$1,100.00		
23	AIR DUCT 1 X SVC	1	\$50.00	\$50.00	*
24	AIR DUCT 2 X SVL	1	\$20.00	\$20.00	+
25	AIR DUCT 3 × SVC	1	\$22.00	\$22.00	X
26	HEADLAMP UPPER BRACKET LH 54 -	1	\$75.00	\$75.00	
27	HEADLAMP UPPER BRACKET RH	1	\$75.00	\$75.00	
28	LOWER REINFORCEMENT ? HIVE	1	\$240.00	\$240.00	+
29	REINFORCEMENT ? +51	1	\$600.00	\$600.00	X
30	RADIATOR ? 4	1	\$550.00	\$550.00	
31	COOLER ? xsn	1	\$750.00	\$750.00	*
32	COOLER PIPE 1 ? FSIC	1	\$350.00	\$350.00	*
33	COOLER HOSE 1 7 45VL	1	\$160.00	\$160.00	X

			Total:	\$19,156.80	
49	ENGINE LOWER COVER X SVC	1	\$200.00	\$200.00	7
48	BONNET LOCK ? LSVL	1	\$210.00		X
47	FENDER RH repur	1	\$480.00	\$480.00	1R
46	FENDER LH 5+	1	\$480.00	\$480.00	
45	BIG ELECTRICAL FAN ?	1	\$850.00	\$850.00	
44	SMALL ELECTRICAL FAN 7. cm/	1	\$500.00	\$500.00	
43	FAN COWL AIR DUCT RH ? FSUC	1	\$55.00	\$55.00	*
42	FAN COWL AIR DUCT LH ? KIN	1	\$55.00	\$55.00	X
41	FAN COWL? de-	1	\$210.00	\$210.00	
40	CONDENSER ? 5+/	1	\$550.00	\$550.00	
39	COOLER VALVE ? +3VL	1	\$210.00	\$210.00	4
38	COOLER AIR PIPE / KSVC	1	\$210.00	\$210.00	X
37	COOLER HOSE 4 7 ASVC	1	\$550.00	\$550.00	X
36	COOLER HOSE 3 / /SVC	1	\$75.00	\$75.00	*
35	COOLER HOSE 2 7 KSVL	1	\$240.00	\$240.00	X
34	COOLER PIPE 2 ", XSA	1	\$220.00	\$220.00	X

10,792.80

ó	S/ No. Job/ Parts Description	Qty/ Ltr	Qty/ Ltr Unit Price	Amount	Remarks	
	FRONT LABOUR					
	TO REPAIR FRT BUMPER, BONNET, CONDENSER RADIATOR HOSES PIPING ETC TO REPAIR FRT SUPPORT PANEL, BOTH DOORS AND A-PILLARS	*****	\$800.00	00088	780	
- 2	TO RESPRAY FRONT BUMPER, LIP SUPPORT PANEL RH LH, FENDER RH LH	4	\$250.00	\$1,000.00	\$00 (9)
0	TO FOCUS DISTANCE SENSORS	-	\$60.00	\$60.00	40/	\
	TO CHECK WIRNG	~	\$40.00	\$40.00	1	
	TO APPLY RUST PROOFING FRONT PORTION	~	\$40.00	\$40.00	\	
	MISCELLENOUS			,		
	SUNDRES	v	\$50.00	\$50.00	2	
			TOTAL:	\$1,990.00		

1 Hy goolooos 8 The good + 2 = 9 aloup L/8 L/8 EXCESSITER RELECT ALLO EXCESSITER RELECT ALLONIN

the Repairer of the following:

• To resurvey before/after spray painting

11,731.52

9713.52

1640,00

- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis Parts prices are subject to confirmation
 - No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

9385.21

Acknowledged by Repairer

1/2-9/4an

			Total:	\$19,156.80	
49	ENGINE LOWER COVER X	1	\$200.00	\$200.00	
48	BONNET LOCK 7. X	1	\$210.00	\$21.0.00	
47	FENDERRH repur	1	\$480.00	\$480.00	
46	FENDER LH 54	1	\$480.00	\$480.00	
45	BIG ELECTRICAL FAN ? *	1	\$850.00	\$850.00	
44	SMALL ELECTRICAL FAM	1	\$500.00	\$500.00	
43	FAN COWL AIR DUCT RH	1	\$55.00	\$55.00	
47	FAN COWL AIR DUCT LH 7 X	1	\$55.00	\$55.00	
41	FAN COWL PRIOR	1	\$210.00	\$210.00	
40	CONDENSER 7.64	1	\$550.00	\$550.00	
39	COOLER VALVE 7 🗡	1	\$210.00	\$210.00	
38	COOLER AIR PIPE	1	\$210.00	\$210.00	
37	COOLER HOSE 4 - X	1	\$550.00	\$550.00	
36	COOLER HOSE 3 7 X	1	\$75.00	\$75.00	
35	COOLER HOSE 2 7	1	\$240.00	\$240.00	
34	COOLER PIPE 2 , X	1	\$220.00	\$220.00	

Battlery tray Bracket cm/
Headlight Nozie (m/
Bumper
Bannet upper Lock bt/
Turbo Hose cut/

\$120 \$85 420 102 \$120 \$120