



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21002196/Qqf3e2-1 Date: 09/03/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4006C	Veh. Inspected	SKX 4996T	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024238	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	16/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TIGUAN	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WVGZZZ5NZGW036823	Colour	BLACK	
Odometer	60323 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40Z R19	DUNLOP	6 mm	
L/H Front Tyre	255/40Z R19	DUNLOP	6 mm	
R/H Rear Tyre	255/40Z R19	DUNLOP	6 mm	
L/H Rear Tyre	255/40Z R19	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2021	Inspection Date	17/02/2021	
Survey held at	3A Ontario AvenueThe Windsor#01-02, S(576192)			
Repairer	MS CAR AUTO PTE LTD			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	