

COMFORTDEL GRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.03.2021

Time: 17:25:17

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305457208
 REGN NO : SHD4041P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 13.12.2017
 DATE/TIME IN : 08.03.2021 10:15
 ACCIDENT DATE : 05.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0577-G	PANEL ASSY-TRUNK LID#	1 L	2,174.90	20.00	1,739.92	/ Buc
0002	04-01-0103-0786-G	EMBLEM-CRDI	1 L	52.40	20.00	41.92	/
0003	04-01-0103-0787-G	EMBLEM-I40	1 L	67.90	20.00	54.32	/
0004	04-01-0103-0800-G	SYMBOL MARK-TRUNK LID	1 L	63.10	20.00	50.48	/ abc.
0005	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.00-	30.00	/
0006	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	0.20	30.00	/
0007	04-01-0103-0584-G	LAMP ASSY-RR COMB I/S LH(	1 L	1,131.20	20.00	904.96	/ SR
0008	04-01-0103-0583-G	LAMP ASSY-RR COMB I/S RH(	1 L	1,131.20	20.00	904.96	/ OA
0009	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1 L	1,106.00	20.00	884.80	X Repair
0010	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/ abc
0011	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	/ abc.
0012	09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	0.20	135.70	X NN
0013	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1 L	228.00	20.00	182.40	? ?

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305457208
REGN NO : SHD4041P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 13.12.2017
DATE/TIME IN : 08.03.2021 10:1
ACCIDENT DATE : 05.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 5,027.06

JOB NATURE

0000 L PANEL BEATING
0001 23-502 SPRAYPAINT ON AFFECTED AREA
0002 17-01 CHECK ALL LIGHTING
0003 20-22 REMOVE/REFIX REVERSE SENSOR

600.00

~~550.00~~ 420

550.00 500

50.00

30

80.00 40

SUB-TOTAL : 1,280.00

TOTAL : 6,307.06

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

3 Days
L/S
After repair photos.
Gua Qian
09/3/21

