



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH NO : SGX722R

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR
NAME : LOW LENG ANN ERIC
ADDRESS :

JOB NO :

CONTACT :

LICENSE NO. SJV3555L TRANS :
MAKE / MODEL : HYUNDAI AVANTE
OWNER'S INSURER : NTUC INCOME
JOB-CODE : TP S/A : JOEYCHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 05-Mar-21

CLAIM DETAIL

MATERIALS	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR- DISP	REV. PRICE
1 FRONT BUMPER 452	1.00	\$ 566.00	20.00	\$ 452.80	Y	✓
2 FRONT BUMPER REINFORCEMENT 255	1.00	\$ 380.00	20.00	\$ 304.00	Y	✓
3 FRONT BUMPER SIDE RETAINER RH	1.00	\$ 42.00	20.00	\$ 33.60	Y	✓
4 FRONT BUMPER SIDE RETAINER LH	1.00	\$ 42.00	20.00	\$ 33.60	Y	X
5 FRONT BUMPER BRACKET RH	1.00	\$ 42.00	20.00	\$ 33.60	Y	X
6 FRONT BUMPER BRACKET LH	1.00	\$ 42.00	20.00	\$ 33.60	Y	X
7 FRONT BUMPER LOWER GRILLE	1.00	\$ 147.00	20.00	\$ 117.60	Y	X
8 FRONT FENDER INNER SHIELD RH	1.00	\$ 158.00	20.00	\$ 126.40	Y	X
9 HEADLAMP LH	1.00	\$ 489.50	20.00	\$ 391.60	Y	X
10 HEADLAMP RH	1.00	\$ 489.50	20.00	\$ 391.60	Y	✓
11 FRONT SUPPORT PANEL 753	1.00	\$ 753.00	20.00	\$ 602.40	Y	✓
12 FRONT SUPPORT PANEL GARNISH	1.00	\$ 218.00	20.00	\$ 174.40	Y	X
13 RADIATOR GRILLE	1.00	\$ 356.90	20.00	\$ 285.52	Y	X
14 RADIATOR GRILLE LOGO	1.00	\$ 50.00	20.00	\$ 40.00	Y	X
15 BONNET	1.00	\$ 1,001.00	20.00	\$ 800.80	Y	X
16 BONNET HINGE LH	1.00	\$ 126.00	20.00	\$ 100.80	Y	X
17 BONNET HINGE RH	1.00	\$ 126.00	20.00	\$ 100.80	Y	X
18 BONNET LOCK	1.00	\$ 84.40	20.00	\$ 67.52	Y	X
19 BONNET INSULATOR	1.00	\$ 168.00	20.00	\$ 134.40	Y	X
20 AIRCON CONDENSOR	1.00	\$ 976.00	20.00	\$ 780.80	Y	X
21 BOOTLID	1.00	\$ 830.00	20.00	\$ 664.00	Y	X
22 BOOTLID EMBLEM AVANTE	1.00	\$ 28.50	20.00	\$ 22.80	Y	✓
23 BOOTLID OUTER GARNISH	1.00	\$ 89.60	20.00	\$ 71.68	Y	X
24 BOOTLID LAMP LH	1.00	\$ 168.00	20.00	\$ 134.40	Y	X
25 BOOTLID LAMP RH	1.00	\$ 168.00	20.00	\$ 134.40	Y	✓
26 BOOTLID INNER LOCK	1.00	\$ 108.50	20.00	\$ 86.80	Y	X
27 BOOTLID CATCH	1.00	\$ 68.00	20.00	\$ 54.40	Y	X
28 BOOTLID CABLE	1.00	\$ 42.80	20.00	\$ 34.24	Y	X
29 BOOTLID RUBBER	1.00	\$ 98.50	20.00	\$ 78.80	Y	X
30 BOOTLID HINGE LH	1.00	\$ 112.70	20.00	\$ 90.16	Y	X
31 BOOTLID HINGE RH	1.00	\$ 112.70	20.00	\$ 90.16	Y	X
32 BOOTLID INNER TRIM	1.00	\$ 328.00	20.00	\$ 262.40	Y	X
33 TAILLAMP LH	1.00	\$ 266.50	20.00	\$ 213.20	Y	X
34 TAILLAMP RH	1.00	\$ 266.50	20.00	\$ 213.20	Y	✓
35 TAILLAMP PANEL LH	1.00	\$ 156.00	20.00	\$ 124.80	Y	X

Not Authorized
L1 Reg @ 8250h
Heavy After Paint
8 days

36	TAILLAMP PANEL RH	SVC	1.00	\$	156.00	20.00	\$	124.80	Y	X
37	REAR BUMPER	B1	1.00	\$	442.00	20.00	\$	353.60	Y	—
38	REAR BUMPER INNER SPONGE	CM	1.00	\$	122.00	20.00	\$	97.60	Y	—
39	REAR BUMPER REINFORCEMENT	B1	1.00	\$	262.00	20.00	\$	209.60	Y	—
40	REAR BUMPER REINFORCEMENT STAY	D17	1.00	\$	134.80	20.00	\$	107.84	Y	—
41	REAR SUPPORT BRACKET 4PCS	CM	4.00	\$	114.00	20.00	\$	91.20	Y	—
42	REAR BUMPER RETAINER LH	SL	1.00	\$	42.50	20.00	\$	34.00	Y	X
43	REAR BUMPER RETAINER RH	D17	1.00	\$	42.50	20.00	\$	34.00	Y	—
44	REAR END PANEL	R	1.00	\$	537.90	20.00	\$	430.32	Y	X
45	REAR END PANEL INNER GARNISH	SL	1.00	\$	129.40	20.00	\$	103.52	Y	X
46	REAR SPARE TYRE BOARD	SL	1.00	\$	220.00	20.00	\$	176.00	Y	X
47	REAR SPARE TYRE	R	1.00	\$	783.00	20.00	\$	626.40	Y	X
48	REAR FENDER INNER TRIM RH	CM	1.00	\$	208.00	20.00	\$	166.40	Y	—
49	REAR FENDER RH	R	1.00	\$	1,603.00	20.00	\$	1,282.40	Y	X
50	REAR FENDER INNER SHIELD RH	SL	1.00	\$	126.00	20.00	\$	100.80	Y	X
51	REAR FENDER AIR VENT RH	SL	1.00	\$	56.00	20.00	\$	44.80	Y	X
52	REAR EXHAUST PIPE	B1	1.00	\$	693.80	20.00	\$	555.04	Y	—
53	REAR EXHAUST PIPE MOUNTING	SL	1.00	\$	105.60	20.00	\$	84.48	Y	X
54	CENTRE EXHAUST PIPE	R	1.00	\$	1,004.00	20.00	\$	803.20	Y	X

TOTAL (PARTS) :

\$ 15,884.10

\$ 12,707.28

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS	ME	1.00	\$	50.00	0.00	\$	50.00	Y	—
2	FRONT NO. PLATE	SD	1.00	\$	50.00	0.00	\$	50.00	Y	45512
4	FRONT FENDER INNER SHIELD CLIPS	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X
	BONNET INSULATOR CLIPS	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X
5	REAR BUMPER CLIPS	ME	1.00	\$	50.00	0.00	\$	50.00	Y	—
6	REAR NO. PLATE	SL	1.00	\$	50.00	0.00	\$	50.00	Y	X
7	REAR END PANEL GARNISH CLIPS	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X
8	REAR FENDER INNER SHIELD CLIPS	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X
9	SPARE TYRE SEALANT	NN	1.00	\$	80.00	0.00	\$	80.00	Y	X
10	REAR END PANEL SEALANT	NN	1.00	\$	80.00	0.00	\$	80.00	Y	X
11	REVERSE SENSOR	CM	1.00	\$	280.00	0.00	\$	280.00	Y	20012
12	REAR WINDSCREEN SEALANT	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X
13	REAR WINDSCREEN INNER SEAL	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X
14	REAR WINDSCREEN CLEANER & PRIMER	NN	1.00	\$	50.00	0.00	\$	50.00	Y	X

TOTAL (PARTS) :

\$ 890.00

\$ 890.00

ABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA - FRONT	1.00	\$	1,400.00	0.00	\$	1,400.00	Y	9001
2	STRAIGHTEN & PANEL BEAT ACCIDENT AREA - REAR	1.00	\$	1,400.00	0.00	\$	1,400.00	Y	70001
3	SPRAY PAINTING ON ACCIDENT AREA - FRONT	1.00	\$	1,400.00	0.00	\$	1,400.00	Y	6001
4	SPRAY PAINTING ON ACCIDENT AREA - REAR	1.00	\$	1,400.00	0.00	\$	1,400.00	Y	8001
5	RESPRAY TUFF KOTE ON ACCIDENT AREA	1.00	\$	180.00	0.00	\$	180.00	Y	X

6	R&R REAR WINDSCREEN GLASS	<i>nn</i>	1.00	\$	120.00	0.00	\$	120.00	Y	<i>X</i>
7	CHECK & REPAIR WIRING SYSTEM		1.00	\$	180.00	0.00	\$	180.00	Y	<i>401</i>
8	R&R AIRCON CONDENSOR & TOP UP GAS		1.00	\$	380.00	0.00	\$	380.00	Y	<i>7 1001</i>
9	R&R BOOTLID COMPARTMENT	<i>nn</i>	1.00	\$	380.00	0.00	\$	380.00	Y	<i>X</i>
10	R&R SEATS, CARPET & TRIM TO ASSIST REPAIR		1.00	\$	120.00	0.00	\$	120.00	Y	<i>601</i>
11	R&R REAR EXHAUST PIPE		1.00	\$	120.00	0.00	\$	120.00	Y	<i>601</i>

TOTAL (LABOUR) : \$ 7,080.00 \$ 7,080.00

TOTAL PARTS & LABOUR \$ 23,854.10 \$ 20,677.28

EXCESS : : \$ \$

NO. OF DAY : *8-10 days*

E-SURVEY : BEFORE / AFTER PAINTING

ART-BY ~~PART~~ OR LUMP-SUM : \$ \$

DATE OF SURVEY : *9, 3, 21*

SURVEY BY : *Henrich*

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SGX722R

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR
NAME : LOW LENG ANN ERIC
ADDRESS :

JOB NO. :

CONTACT :

LICENSE NO. SJV355SL TRANS. :
MAKE / MODEL : HYUNDAI AVANTE
OWNER'S INSURER : NTUC INCOME
JOB-CODE : TP S/A : JOEY
SUPPLEMENTARY
CLAIM DETAIL

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 05-Mar-21

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR- DISP	REV. PRICE
1 FRONT BUMPER SPONGE 118.60	CM 1.00	\$ 135.80	20.00	\$ 108.64	Y	✓
2 FOG LAMP RH 285	m3em 1.00	\$ 395.00	20.00	\$ 316.00	Y	✓
3 WASHER TANK	Red 1.00	\$ 93.00	20.00	\$ 74.40	Y	✓

EXCESS : : \$ \$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$ \$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT NO. :

FAX NO. :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.