



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003103/EKtf3n2 Date: 29/04/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBP 1449A	Veh. Inspected	SLX 1584G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2100650/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	09/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHD841CMJU648523	Colour	BEIGE	
Odometer	44874 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	5 mm	
L/H Front Tyre	205/55 R16	KUMHO	5 mm	
R/H Rear Tyre	205/55 R16	KUMHO	5 mm	
L/H Rear Tyre	205/55 R16	KUMHO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2021	Inspection Date	29/03/2021	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	