



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 37885

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING
78 SHENTON WAY
#07-16

SINGAPORE 079120

ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 08/03/2021

CLAIM NO. : 11693

POLICY NO. : PNMC2020-00002819

FROM : HASRIANAH

VEHICLE NO. : FBQ0930C

MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
2	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
3	BOX REAR KAPPA K47 MANTA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$300.00	300.00
4	BRACKET BOX REAR (GIVI) P/N: 55428 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	65.00
5	COVER SIDE CENTRE RH (WHITE) P/N: 58117 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
6	COWLING FRONT RH (WHITE) P/N: 59594 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
7	EMBLEM (ABS) P/N: 56578 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$11.00	22.00
8	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
9	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$73.00	73.00

*37885 *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2022-1-0383
ISO 9001:2015

Quotation Nos. : 37885

(Page 2 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
10	GASKET EXHAUST PIPE P/N: 58162 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$13.00	13.00
11	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$63.00	504.00
12	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$240.00	240.00
13	MIRROR RH P/N: 58187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
14	MUDGUARD FRONT (WHITE) P/N: 58087 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
15	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	54.00
16	PANEL 2 (MATTE BLACK) RH P/N: 63492 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00
17	PIPE EXHAUST ASSY P/N: 58083 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$423.00	423.00
18	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00
19	PROTECTOR EXHAUST P/N: 58086 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
20	REFLECTOR ASSY REAR P/N: 63813 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
21	REFLECTOR REAR P/N: 67563 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
22	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$2.00	10.00

SUB TOTAL

\$2,075.00

GST @ 7 %

\$145.25

GRAND TOTAL (SGD)

\$2,220.25

50% deposit required before ordering of parts.

Validity: 30 days

*37885 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
 Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

 CERT NO: 2022-1-07883
 ISO 9001: 2015

Quotation Nos. : 37885

(Page 3 of 3)

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*37885 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | **Telephone:** +65 6281 6520 | **Web:** www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 8759