

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/C7/21003/13/ues3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

___ S + RS. ___ SI

) Photos

) Others

TOTAL

N/S	O/S

10/3/24 4/5 \$1200 confirmed with kerliang

no video have accident scene photo

Broox

Vehicle: IN / OUT

LTA \$21258

N/S Frt.

KAI LIANG MOTOR SERVICE
BLK 1 KAKI BUKIT AVE 6 #01-101
AUTO BAY@KAKI BUKIT
S'PORE 417883 TEL: 67474189

VEHICLE NO : GBJ 8373U

NETT ITEM

1PC	FRONT BUMPER	32	\$571.90	✓
1PC	FRONT BUMPER BEAM		\$320.00	X
1PC	FRONT BUMPER SIDE HOLDER N/S	un	\$161.70	X
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	garnish	\$107.50	✓
1SET	FRONT BUMPER CLIPS	men	\$30.00	✓
1PC	HEADLAMP N/S	scr	\$401.70	✓
1PC	FRONT CORNER PANEL N/S	un	\$355.20	X
			\$1,948.00	

TO CHECK WIRING

\$50.00 20

TO SPRAY RUST PROOFING

11 \$50.00 X

TO RESET & REPROGRAMME SYSTEM CLEAR FAULT CODE

\$80.00 50

LABOUR FOR PANEL BEATING & REPLACED PARTS

\$300.00 250

TO PUTTY & SPRAY PAINTING

\$450.00 200

TOTAL \$2,878.00

Not Authorised
LKR
2/s \$1200/
2 days

* LKR Asker

P-1111-10
102
999.99
1519.99
202
1215

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: