

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

8-Mar-21

Our ref : TP/4958/21

Yeow Teck Hoe

TPAIG.
Jasper

JTHBK262705087324

RE : estimate cost for vehicle no : SJJ 9057G

1 pc	bonnet (Aluminium) Bueled	\$	2,253.10	✓	1859
1 pc	frt bumper Dehd		880.00	✓	
2 pcs	frt bumper retainer ne		150.00	✓	
1 pc	frt bumper lower grille Dehd		105.00	✓	
1 pc photo	frt bumper reinforcement Best		575.00	✓	
1 pc photo	frt bumper sponge Dehd		95.00	✓	
1 pc	frt bumper top rubber ne		65.00	+	
1 pc	frt grille cut out		473.00	✓	
1 pc	frt grille logo on		80.00	✓	
1 pc	frt grille chrome at		310.00	✓	
1 pc	frt no plate base Dehd		120.00	✓	
2 pcs photo	headlamp cut		2,400.00	✓	
1 pc	frt support panel Rev		1,245.00	+	
1 pc	frt support panel top garnish Dehd		475.00	✓	
1 pc	bootlid Bueled		720.00	✓	
1 pc	bootlid lock Dehd		499.00	✓	
1 pc	bootlid w/strip 2t		235.00	✓	
1 pc	bootlid logo 2		85.00	✓	
1 pc	IS 250 emblem per		75.00	✓	
1 pc	Lexus emblem		80.00	✓	
2 pcs	bootlid reflector RH at		995.60	✓	1857.80
1 pc	bootlid insulator ne		367.80	+	
14 pcs	bootlid insulator clips ne		84.00	+	
1 pc	rear no plate garnish Dehd		1630.00	✓	758
2 pcs	taillamp at		1138.80	✓	
1 pc	rear bumper Dehd		890.00	✓	
2 pcs	rear bumper retainer long 3 ne		270.00	✓	
2 pcs	rear bumper retainer short		160.00	✓	
2 pcs	rear bumper reflector ne		240.00	+	
2 pcs	rear bumper tow hook cover Dehd		43.00	✓	
1 pc	rear bumper reinforcement Best		465.00	✓	
2 pcs	rear bumper bracket Best		150.00	✓	
1 pc	rear bumper sponge cut		135.00	✓	
6 pcs	rear bumper clips ne		36.00	✓	
1 pc	end panel Dehd		765.00	✓	
			18290.30		

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SJJ 9057G

Bal brought forward: \$ 18,290.30

1 pc	end panel inner garnish	15557.40	365.00	✓
1 pc	spare tyre cardboard		415.00	✓
2 pcs	rear fender inner trim	14001.66	1,169.00	+
1 pc	tool box		165.80	✓
2 pcs	rear no plate lamp		301.70	+

20,706.80

less 10%

2,070.68

18,636.12

1 pc	frt no plate	290	40.00	snett ✓
1 pc	rear no plate		40.00	+
1 pc	reverse sensor		250.00	✓

Panel beating. 1,800.00 1600

Spray painting. 1,800.00 1400

Top up gas. 120.00 +

Rust proofing. 80.00 ✓

Wiring. (frt & rear) 60.00 ✓

22,826.12

1,597.83

24,423.95

To remove reverse sensor

To remove upholstery

To transfer bottle fittings

10050

15080

15060

Plus 7% GST

SD : Twenty-four thousand four hundred twenty-three & cents ninety-five only.

Adnan L
L/S 08/03/21

10 Days

Supplementary : 123.26

Total : 17744.92

L/S : 14.2K

142K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

9-Mar-21

Our ref : TP/4958/21

Yeow Teck Hoe

RE : Supplementary cost for vehicle no : SJJ 9057G

2 pcs	taillamp garnish	ut	\$	128.00
			less 10%	12.80
				115.20
			Plus 7% GST	8.06
				123.26

SD : One hundred twenty-three & cents twenty-six only.

Supplementary: 123.26