

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

TP Clinic
Veron

Contact : 96369376

ESTIMATE

Repair Code : CLM16720
 Date in : 05/03/2021
 Vehicle Num. : SMG6101L
 Model : HONDA SHUTTLE HYBRID 1.5 AUTO
 Chassis/Eng# : GP72000329/LEB7100551

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>rehd</i>	1	1050.00	✓ 1,050.00
FRONT BUMPER GRILLE <i>Not a</i>	1	140.00	+ 140.00
FRONT BUMPER LOWER COVER <i>not torn</i>	1	210.40	✓ 210.40
FRONT BUMPER LOWER PANEL <i>Repair</i>	1	760.40	+ 760.40
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	420.90	✓ 420.90
FRONT BUMPER RH AIR GUIDE <i>not a</i>	1	50.10	+ 50.10
FRONT BUMPER RH FOGLAMP <i>cancel</i>	1	344.10	✓ 344.10
FRONT BUMPER RH FOGLAMP COVER <i>not a</i>	1	35.00	+ 35.00
FRONT BUMPER RH FOGLAMP GARNISH <i>not a</i>	1	33.20	+ 33.20
FRONT BUMPER SIDE RETAINER L/R <i>RH Rhd</i>	2	15.70	15.70 31.40
FRONT BUMPER TOW HOOK COVER <i>not a</i>	1	58.20	✓ 58.20
FRONT GRILLE <i>cancel</i>	1	395.00	— 395.00
FRONT GRILLE 'LOGO' EMBLEM <i>not a</i>	1	23.40	— 23.40
FRONT GRILLE BRACKET <i>not a</i>	1	65.00	T 65.00
FRONT GRILLE LOWER CHROME MOULDING <i>cancel</i>	1	231.75	✓ 231.75
FRONT GRILLE UPPER CHROME MOULDING <i>cancel</i>	1	302.50	✓ 302.50
FRONT RH FENDER 'HYBRID' EMBLEM <i>not a</i>	1	75.80	✓ 75.80
FRONT RH FENDER SHIELD <i>Not a</i>	1	110.50	+ 110.50

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 96369376

ESTIMATE

Repair Code : CLM16720
 Date in : 05/03/2021
 Vehicle Num. : SMG6101L
 Model : HONDA SHUTTLE HYBRID 1.5 AUTO
 Chassis/Eng# : GP72000329/LEB7100551

FRONT RH HEADLAMP	<i>cancel</i>	1	2250.00	✓	2,250.00
FRONT RH HEADLAMP CHROME MOULDING	<i>per u</i>	1	86.00	+	86.00
FRONT RH HEADLAMP LOWER BRACKET	<i>cancel</i>	1	38.00	✓	38.00
WASHER TANK	<i>per u</i>	1	75.00	✓	75.00
Subtotal before discount					6,786.65
Percentage discount 20%					1,357.33
Sub-total 1					5,429.32
FRONT BUMPER CLIPS - SET	<i>per u</i>	1	50.00	30	50.00
FRONT BUMPER LOWER COVER CLIPS - SET	<i>per u</i>	1	30.00	+	30.00
FRONT GRILLE CLIPS - SET	<i>per u</i>	1	30.00	✓	30.00
FRONT RH FENDER SHIELD CLIPS - SET	<i>per u</i>	1	50.00	+	50.00
RADIATOR COOLANT	<i>per u</i>	1	50.00	+	50.00
Subtotal before discount					210.00
Percentage discount 0%					0.00
Sub-total 2					210.00
Parts-total					5,639.32

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR) ~~120.00~~

To remove, reinstall electrical wiring harness, check lighting. (to FR) ~~30~~ 50.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 96369376

ESTIMATE

Repair Code : CLM16720
Date in : 05/03/2021
Vehicle Num. : SMG6101L
Model : HONDA SHUTTLE HYBRID 1.5 AUTO
Chassis/Eng# : GP72000329/LEB7100551

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	500	850.00
1060	500	850.00
	30	50.00
Labour Total		1,920.00
Parts & Labour Total		7,559.32

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
H/S 22/03/21
04 Days.

total: 5504.60

H/S: A.H.K. ✓