

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 10 Mar 2021

Preliminary Advice

Vehicle No	: SLZ2056Y	Accident Date	: 04/03/2021
Make	: MITSUBISHI ATTRAGE	Policy No.	: DMPCSNW00041892000
Assignment Date	: 09/03/2021	Excess	: S\$500.00
Date of Inspection	: 10/03/2021	Est. Duration of Repair	: 14
Inspection At	: ALAN'S UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,089.40
Revised Amount	:S\$	9,877.80
Check Items (Estimated)	:S\$	3,789.50
Total	:S\$	13,667.30
Lump Sum Repair	:S\$	10,950.00 (estimate)

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	51,000.00
COE / PARF Rebate	:S\$	30,163.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,837.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.