

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21003170/Ars3q2
	8 SHENTON WAY AXA TOWERSING			Date:	03/11/2021
	ATTN:CHAN KIAN	CHUAN		Code:	ASM
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 8187S	Veh. Inspected	i	SJY 6177J
	Policy No.	P2419140	Coverage (\$)		0.00
	Claim No.	S1M034W0	Excess (\$)		0.00
	Assign From		Assign Date		10/03/2021
2. Vehicle Particulars & Condition					
	Make & Model	SEAT LEON	c.c		999
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	VSSZZZ5FZJR055873	Colour		MAROON
	Odometer	61067 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/55 R16	MICHELIN		6 mm
	L/H Front Tyre	205/55 R16	MICHELIN		6 mm
	R/H Rear Tyre	205/55 R16	MICHELIN		6 mm
	L/H Rear Tyre	205/55 R16	MICHELIN		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/03/2021	Inspection Dat	e	10/03/2021
	Survey held at	MG SOLUTION PTE LTD			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	<u> </u>				