

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0199/2021/HR
DATE : 9-Mar-21
WIP : 18674

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/2/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. DICKSON CHU TEE CHEN (CHU DICHEN)
ADDRESS : 47 MANDALAY ROAD
#04-03
SINGAPORE 308227
TELEPHONE : HP +65 8292 7234
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070117345
VEHICLE NO : **SKB 606 L**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 11/8/2020
ENGINE NO : CZD 893845
CHASSIS NO : WAUZZZF38L1105853
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Mar-21
PLACE OF ACCIDENT : BALESTIER ROAD, OPPOSITE AH HOOD ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKB 606 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	259
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER & LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$	2,400.00	500
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,500.00	400
5	TO CARRY OUT DIAGNOSTIC CHECK.	\$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 5,972.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKB 606 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>del</i>	1	\$ 2,161.00	✓	
2	FRONT BUMPER END PLATE SHORT - LH	1	\$ 59.00	X	
3	FRONT BUMPER LOWER GRILLE - LH	1	\$ 110.00	X	
4	FRONT BUMPER END PLATE LONG	1	\$ 190.00	X	
5	FRONT BUMPER SPOILER <i>at</i>	1	\$ 383.00	✓	
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>near at</i>	1	\$ 153.00	✓	
7	FRONT BUMPER GUIDE SECTION - LH	1	\$ 39.00	?	
8	FRONT BUMPER FOAM FILLER	1	\$ 102.00	X	
9	FRONT BUMPER IMPACT BAR	1	\$ 916.00	X	
10	FRONT FENDER - LH <i>Regis</i>	1	\$ 1,286.00	X	
11	FRONT FENDER ATTACHMENT PARTS - LH <i>new</i>	1	\$ 63.00	X	
12	FRONT FENDER BRACE - LH	1	\$ 88.00	X	
13	FRONT FENDER BRACKET - LH	1	\$ 32.00	X	
14	FRONT FENDER WHEEL HOUSING LINER - LH	1	\$ 240.00	X	
15	WHEEL HOUSING LINER ATTACHMENT PARTS F/R	1	\$ 101.00	X	
16	FRONT FENDER COVER - LH	1	\$ 16.00	X	
17	HEADLIGHT LAMP BRACKET - LH	1	\$ 118.00	X	
18	LED HEADLIGHT - LH <i>at</i>	1	\$ 5,589.00	✓	
19	HEADLIGHT LIFT CYLINDER - LH <i>new</i>	1	\$ 210.00	X	
20	FRONT FENDER WHEEL COVER - LH / RH <i>LH at, RH at</i>	2	\$ 536.00	✓	
21	SUNDRIES		\$ 250.00	?	
TOTAL SPARE PARTS			\$ 12,642.00		
TOTAL LABOUR CHARGES			\$ 5,972.00		
GRAND TOTAL			\$ 18,614.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian Ly
10/03/21

are Authorised, OK Pyp

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: