



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/S Grab Rentals Pte Ltd
	Document No. 0	6 Battery Road #38-04 Singapore 049909
	Document Date 15/03/2021	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	02/06/2017	SLP3967P	0	60546	66TP/SLP3967P/080321

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FUX03559956	2ZRS052153	60	Shashitharan	11/03/2021 8.00	15/03/2021 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SLF9470T ACC DATE:07/03/21 DRIVE IN:10/03/21 DATE-IN:10/03/21 DATE SURVEY:11/03/21 NO OF REPAIR DAYS:4 BY:steve AUTHORIZED ON:				50.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST	*			180.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR	*			180.00
4	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALIGN ACC AFF AREA	*			720.00
5	B	BP-RES2 RESRPAY ACC AFF AREA	*			1180.00
6	1	U52023-47030 REINFORCEMENT	1.00	332.70		332.70
7	2	U52159-47913 COVER, RR BUMPER	1.00	442.60		442.60
8	3	K52161-0K040 PIECE, RR BUMPER	4.00	4.10		16.40
9	4	U75403-48010 EMBLEM SUB-ASSY,	1.00	47.90		47.90
10	5	U75441-47130 PLATE, LUGGAGE COMPT	1.00	54.60		54.60
11	6	U75442-47130 PLATE, LUGGAGE COMPT	1.00	54.60		54.60
12	7	SPC507-47001 16 BACK SENSOR WHITE PEARL SILVER	1.00	169.60		169.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			3,428.40
	Please acknowledge receipt of vehicle	Parts 1,118.40	GST 7.00% 239.99
		Labour 2,310.00	Less 0.00
		Sublet 0.00	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 3,668.39

Customer Copy