



Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklilmotorsport.com.sg Website: www.hklilmotorsport.com.sg

FBH5256E

1	METER ASSY	\$450
2	FRONT FORK ASSY LH/RH	\$650
3	FRONT FORK UNDER BRACKET	\$220
4	STEERING CONE BEARING	\$90
5	BODY FRAME ALIGNMENT	\$680
6	FRONT FENDER	\$150
7	FRONT WHEEL RIM	\$380
8	FRONT WHEEL SHALF	\$35
9	FRONT WHEEL BEARING 2PCS	\$40
10	FRONT WHEEL BEARING OIL SEAL	\$15
11	FRONT BRAKE DISC	\$220
12	FRONT BRAKE CALIPER	\$250
13	HEAD COWLING LH/RH	\$180
14	FRONT SIGNALS LH/RH	\$120
15	IU UNIT	\$170
16	IU UNIT BRACKET	\$35
17	HANDLE BAR LH	\$120
18	HANDLE BAR GRIP	\$40
19	HANDLE BAR BALANCER	\$120
20	WINDSHIELD	\$80
21	FRONT NO PLATE	\$15
22	BRAKE LEVER	\$45
23	SIDE MIRROR LH/RH	\$160
24	HEADLIGHT	\$320
25	HEADLIGHT PANEL	\$80
26	FRONT BRAKE PUMP ASSY	\$220
27	FRONT FENDER BRACKET	\$55
28	CRASHBAR SET	\$280
29	CRASHBAR CLOTH	\$60
30	BRAKE PEDAL	\$70
31	FRONT FOOT REST RH	\$45
32	FRONT FOOT REST BRACKET RH	\$120
33	FUEL TANK COVER	\$250
34	TOP BOX	\$350
35	REAR FOOT REST RH	\$45
36	REAR NO PLATE	\$15
37	TOWING	\$45
38	LABOUR	\$680

TOTAL AMOUNT:

\$6,900