

### CONNECT 3

566 Woodlands Road ( Mandai Estate ) Singapore 728697  
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L  
G S T : 5 3 3 6 0 0 6 1 L

QT21/PC2045C/TPC

<b>China Taiping Insurance (Singapore) Pte Ltd</b>
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

### QUOTATION

Dear Sir,  
Cost of Repair to Vehicle PC2045C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Rear bumper / CR4.	1	1,750.00	1,750.00	1,620
2.	Rear bumper LH bracket / BT.	1	350.00	350.00	✓
3.	Rear LH side panel XR	1	3,700.00	3,700.00	X
4.	Rear LH side reflector lamp / SCK	1	185.00	185.00	✓
5.	Remove & refit Lh side glasses to assist repair X	1	900.00	900.00	X 2,155
6.	Remove & refit inner trim, seats etc to assist repair X	1	300.00	300.00	X 102
7.	Sealant X	4	40.00	160.00	X 1,939.50
8.	Check wiring	1	20.00	20.00	✓
9.	Labour charges	1	1,500.00	1,500.00	900
10.	Spray painting	1	2,400.00	2,400.00	2,000
<b>SUB-TOTAL</b>				<b>S\$11,265.00</b>	2,920


- Price before 7% gst

Repair day 5 days  
L/S  
After paint photo.  
Sun Pin (Lth)  
12/03/2021  
TP without prejudice

1,939.50	
2,920	
4,859.50	
- 20%	
3,887.60	L/S \$ 3,900 5 days

Thank you.

Yours faithfully,



Winnie Chai  
HP: 9850-9666