REPAIR ESTIMATE*

VEHICLE'NO SHD4658K

DATE 10/11/20 12:00 AM

MAKE

/ CHIANG/CHINA

MODEL	: HYUNDAI IONIQ G3		7 CHIANO/CHIA	Amount
Qty	Parts Description/ Labour	Туре	Unit Price	
	1 FRONT RH DOOR PANEL		b /	\$1,797.20
	1 REAR RH DOOR PANEL			\$1,789.90
H .	1 REAR DOOR OUTER MOULDING RH		av	\$168.50
	1 FRONT DOOR KEY LOCK SET		NN	\$353.50
	1 FRONT DOOR OUTER HANDLE RH		C.	\$234.80
	1 FRONT DOOR OUTER MOULDING RH		Cu	\$110.10
	SUB TOTAL		2310 · 60·	\$4,454.00
	LESS 20%		12 48 48	\$890.80
	DISCOUNTED TOTAL		1870 10	\$3,563.20
	1 FRONT DOOR COMFORT LOGO STICKER 1 REAR DOOR COMFORT APP STICKER Labour Charge Panel Beating Spray Painting Charge Remove/refix door parts Check Wiring TOTAL LABOUR		155	\$75.00 \$80.00 \$165.00 \$800.00 \$600.00 \$120.00 \$60.00 \$1,580.00
	ESTIMATE TOTAL		\$3118.48 3 days	\$5,308.20
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basi
- No illegal modification(s) is allowed
- Supplementary item(a) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed