# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

20 McCallum Street

#09-01 Tokio Marine Centre

Singapore 069046

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Ng Kwai Kay Francis Date: 16 Mar 2021

## **Preliminary Advice**

Vehicle No : SMA7104D Accident Date : 09/03/2021 Make : TOYOTA CAMRY Policy No. : MT105550 Assignment Date : 12/03/2021 **Excess** : S\$800.00

Date of Inspection : 12/03/2021 Est. Duration of Repair : 0

Inspection At : CHIN MENG MOTORS (HQ)

1 KAKI BUKIT AVE 6 #01-40/63, AUTOBAY @ KAKI BUKIT

SINGAPORE 417883

### Point of Impact / General Description of Damages

The vehicle caught fire.

| Repairer's Estimate (Gross) | :S\$ | TOTAL LOSS |
|-----------------------------|------|------------|
| Revised Amount              | :S\$ | TOTAL LOSS |
| Check Items (Estimated)     | :S\$ | 0.00       |
| Total                       | :S\$ | 0.00       |
|                             |      |            |

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

48,000.00 Pre-Accident Value :S\$ COE / PARF Rebate 24,990.00 :S\$

Salvage Value :S\$

Margin for Repair 23,010.00 :S\$

### Remarks

| )  | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage Kindly let us have your authorisation. |
|----|--|
| Χ) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.  |
| )  | Other comments:  |