

## SINGAPORE CIVIL DEFENCE FORCE

## FIRE REPORT

| 1. GENERAL INFORMATION   |  |
|--|--|
| INCIDENT NO. : /20210309/0643  | LOCATION OF FIRE:                                |
| FIRE REPORTED ON: 09 March 2021  | Open space car park beside                       |
| TIME OF CALL: 18:02:45 hrs   | Block 102, Bedok North Avenue 4 Singapore 460102 |
| STATION COVERAGE: Changi Fire Station  |  |
| 2. INCIDENT INFORMATION  |  |
| FIRE INVOLVED: The engine compartment of a Toyota car (SMA7104D) at parking lot no. 87.  |  |
| METHOD OF EXTINGUISHMENT: By SPF officer using a dry powder fire extinguisher prior to the arrival of SCDF crew.   |  |
| PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the engine compartment)   |  |
| DAMAGE SUSTAINED: As a result of the fire, the engine compartment, headlight, bonnet and the front of the car were damaged. The car windscreen sustained varying degrees of heat and smoke damage. |  |
| Forcible entry was conducted on the bonnet for firefighting.   |  |

ADDRESS

NIL

DEAD/INJURIES SUSTAINED

NIL

## REPORT CERTIFIED TRUE AND CORRECT BY:

PIN/FIN

NIL

EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE

3. FATALITY/INJURY INFORMATION

NIL

NAME

This is a computer generated Fire Report. No signature is required.