



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III21000284/Gqd3e2-1	
			Date: 09/04/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3603A	Veh. Inspected	SJX 3166R	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20120617	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	12/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A3 1.8T	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	TRUZZZ8P7A1004423	Colour	BLACK	
Odometer	94796 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R17	MICHELIN	6 mm	
L/H Front Tyre	225/45Z R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45Z R17	MICHELIN	6 mm	
L/H Rear Tyre	225/45Z R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/12/2020	Inspection Date	18/01/2021	
Survey held at	2 KAKI BUKIT AVE 2#02-02 AUTOHUB			
Repairer	MW BROTHERS AUTO REPAIRS			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	