

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



| NTUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: | NS/INC21003282/Qqd3n2 | |
|--|---|-------------------------|---------|-----------------------|------------|
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: | 29-04-2021 INC4 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | GBF 7312Z | Veh. Ir | spected | SHC 4827U |
| | Policy No. | 5121090761 | Covera | age (\$) | 0.00 |
| | Claim No. | MT/1123842-002 | Exces | s (\$) | 0.00 |
| | Assign From | | Assign | n Date | 11/03/2021 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | TOYOTA PRIUS | c.c | | 1798 |
| | Engine No. | HIDDEN | Year o | f Reg. | 2016 |
| | Chassis No. | JTDKN36U405767939 | Coloui | ſ | MAROON |
| | Odometer | 387440 | Steerii | ng | IN ORDER |
| | Brakes | IN ORDER | Modifi | cation | SPORTS RIM |
| | General | FAIR | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 195/65 R15 | SAILUN | l | 6 mm |
| | L/H Front Tyre | 195/65 R15 | SAILUN | l | 6 mm |
| | R/H Rear Tyre | 195/65 R15 | SAILUN | | 6 mm |
| | L/H Rear Tyre | 195/65 R15 | SAILUN | l | 6 mm |
| 4. Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 09/03/2021 | Inspec | tion Date | 11/03/2021 |
| | Survey held at | SMRT AUTOMOTIVE SERVICE | S PTE L | ΓD | |
| | 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 | | | | |
| 5a. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | |