

KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721
TEL: 6457-8629 FAX: 6451-7651
UEN No 201923475D

DATE 17TH Mar 2021
OUR REF GBG 3191 B
FRIENDLY VEGETARIAN FOOD SUPPLIER
TO BLK 421 ANG MO KIO AVENUE 10
#01-1165
SINGAPORE 560421
RE QUOTATION FOR VEHICLE GBG 3191 B - NISSAN URVAN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR NETT ITEMS

Quantity	Item	Unit Price (S\$)	Amount (S\$)
1	Front Panel / <i>DD</i>		1,221.50 / <i>1,213.21</i>
1	Front Grille / <i>DD</i>		479.30 / <i>479.30</i>
6pcs	Front Grille Clips / <i>Nec</i>	3.10	18.60 / <i>18.60</i>
SUB-TOTAL			1,719.40 / <i>1,711.11</i>
LESS 10% DISCOUNT			171.94 / <i>-10%</i>
TOTAL			1,547.46 / <i>1,540</i>

FOR LABOUR CHARGES

Item	Amount (S\$)
Panel Beating	600.00 / <i>500</i>
Spray Painting	500.00 / <i>250</i>
Labour to remove and refit dashboard to facilitate repair	250.00 / <i>150</i>
Labour to remove and refit aircon cooling coil, blower motor and to refill reffridgerant	250.00 / <i>150</i>
To replace advertisement sticker / <i>Nec</i>	400.00 / <i>150</i>
To check wirings and lightings	50.00 / <i>30</i>
Sealant for front panel	60.00 / <i>30</i>
TOTAL	2,110.00 / <i>1,260</i>

GRAND TOTAL FOR THIS QUOTATION 3,657.46

Repair day 3 days

P/P

before paint photo.

Sun Pm (LKK)
16/03/2021
TP within program

1,540
1,260
2,800

P/P
\$ 2,800
3 days