

KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-10, SINGAPORE 575721
TEL: 6457-8629 FAX: 6451-7651
UEN No 201923475D

DATE 17TH Mar 2021
OUR REF GBG 3191 B
FRIENDLY VEGETARIAN FOOD SUPPLIER
TO BLK 421 ANG MO KIO AVENUE 10
#01-1165
SINGAPORE 560421
RE QUOTATION FOR VEHICLE GBG 3191 B - NISSAN URVAN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR NETT ITEMS

Quantity	Item	Unit Price (S\$)	Amount (S\$)
1	Front Panel / DD		1,221.50
1	Front Grille / DD		479.30
6pcs	Front Grille Clips / Nec	3.10	18.60
SUB-TOTAL			1,719.40
LESS 10% DISCOUNT			171.94
TOTAL			1,547.46

FOR LABOUR CHARGES

Item	Amount (S\$)
Panel Beating	600.00
Spray Painting	500.00
Labour to remove and refit dashboard to facilitate repair	250.00
Labour to remove and refit aircon cooling coil, blower motor and to refill reffridgerant	250.00
To replace advertisement sticker / Nec	400.00
To check wirings and lightings	50.00
Sealant for front panel	60.00
TOTAL	2,110.00

GRAND TOTAL FOR THIS QUOTATION 3,657.46

Repair day 3 days

P/P

before paint photo.

Sun Pm (LKK)
16/03/2021
TP within program

1,540
1,260
2,800

P/P
\$ 2,800

8 days
5