

Ulu: Asher

not Authorized
15/3/21
4/58 5500

4 days.

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: SMU 9392U

S.NETT

1PC	FRONT BUMPER	Del cur	2200	\$2,219.00	—
1PC	FRONT BUMPER SIDE RETAINER O/S	one	66.00	\$105.00	—
1SET	FRONT BUMPER CLIPS	one	50.00	\$60.00	—
1PC	FRONT BUMPER FOG LAMP O/S	one	172	\$620.00	—
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	one	145	\$205.00	—
1PC	FRONT BUMPER REINFORCEMENT	one		\$713.00	X
1PC	HEADLAMP O/S	one	1308	\$4,850.00	—
1PC	HEADLAMP LOWER BRACKET O/S	one	118	\$395.00	—
1PC	FRONT SUPPORT PANEL	one		\$1,250.00	X
1PC	FRONT GRILLE	one	706	\$1,480.00	—
1PC	FRONT GRILLE LOGO	one		\$115.00	X
1PC	FRONT FENDER O/S	Del/cur	990	\$1,280.00	—
1PC	FRONT FENDER INNER SHIELD O/S	Del/cur	240	\$292.00	—
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	one		\$60.00	—
1PC	FRONT SPORT RIM O/S	one		\$1,200.00	X
				\$14,844.00	

TO CHECK WIRING
TO CONDUCT WHEEL ALIGNMENT
TO REFILL AIR CON GAS
TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 30
11 \$120.00 X
11 \$120.00 X
11 \$180.00 X
\$1,080.00 500
\$1,000.00 600
TOTAL \$17,394.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-6055
52
P-5752.25
L. 1130.00
6882.25
20
8505