



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003360/T1vf3e2	
			Date: 08/07/2021	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YN 5910X
	Policy No.	D21MTPCVE000272	Coverage (\$)	0.00
	Claim No.	CMTD2100633	Excess (\$)	750.00
	Assign From	AGNES CHAN	Assign Date	15/03/2021
2. Vehicle Particulars & Condition				
	Make & Model	ISUZU NMR85	c.c	2999
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JAANMR85HE7101557	Colour	WHITE
	Odometer	120571 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/85 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	195/85 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/85 R16 (D)	BRIDGESTONE	3/3 mm
	L/H Rear Tyre	195/85 R16 (D)	BRIDGESTONE	3/3 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/02/2021	Inspection Date	15/03/2021
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A)THE MARKET VALUE IS S\$34,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		21 Working Days	