

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : Sompso Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 21/SP/OD-110(03)
Claim Type : OD CLAIM
Accident Date : 25/02/2021

Claim No :
No :
Date : 19/04/2021
Policy No : D21MTPCVE000272
Veh Reg No : YN5910X
Make / Model : ISUZU NMR85
Chasis No : 0
Engine No:
Reg. No :

SUPPLEMENTARY FOR VEHICLE NO: YN5910X

	Discription	Quantity	List Price	Amount
	<u>Cost Price</u>			S\$ S\$
1	FRT RH PILLAR ANTENNA	1 PC		\$95.00
		TOTAL		<u>\$95.00</u>

P
Parts 3545
SN 7065
LC 1480
12,090

19/04/2021

Amount Before Excess	\$95.00
Add GST @7%	\$6.65
Total Amount Payable	<u>\$101.65</u>

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

- Labour
- 1 WIRE CHECKING
 - 2 TRANSFER DOOR COMPONENT
 - 3 LABOUR CHARGE
 - 4 SPRAY PAINTING

\$30.00 ✓
 \$100.00 50
 \$750.00 700
 \$850.00 700
 \$1,730.00

1480

Amount Before Excess	\$15,583.00
Less Excess	\$0.00
Amount Before GST	\$15,583.00
Add GST @7%	\$1,040.81
Total Amount Payable	\$16,623.81

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

Tanpin 97495747 / 62563561

'wp' Not Authorise Limit - \$1610

Revert EXP: to be advise \$750

Tanpin @ 1/10/2010

0 8 days front panel

14 days - Rear box

Sumatra Repair after repair
 P/P Repair new parts.

Repairing repair wly

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

M/S : Sompso Insurance Singapore Pte Ltd
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 21/SP/OD-110 (03)
Claim Type : OD CLAIM
Accident Date : 25/02/2021

Claim No :
No :
Date : 11/03/2021
Policy No : D21MTPCVE000272
Veh Reg No : YN5910X
Make / Model : ISUZU NMR85UH5A
Chassis No : JAANMR85HE7101557
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: YN5910X

Discription	Quantity	List Price	Amount
Cost Price			S\$
1 FRT RH DOOR	1 PC	\$820.00	bt
2 FRT RH DOOR OUTER HANDLE	1 PC	\$95.00	cut
3 FRT RH DOOR SIGNAL LAMP	1 PC	\$115.00	cut
4 FRT RH DOOR STEP GARNISH	1 PC	\$165.00	cut
5 FRT RH DOOR LOWER HINGE	1 PC	\$95.00	cut
6 FRT RH CORNER PANEL	1 PC	\$240.00	cut
7 FRT RH CORNER PANEL SIDE RUBBER	1 PC	\$75.00	cut
8 FRT RH CORNER PANEL TOP COVER	1 PC	\$95.00	cut
9 HEADLAMP RH	1 PC	\$350.00	cut
10 HEADLAMP LOWER RUBBER	1 PC	\$30.00	cut
11 FRT BUMPER	1 PC	\$400.00	cut
12 FRT BUMPER BRACKET RH	1 PC	\$150.00	bt
13 FOG LAMP RH	1 PC	\$280.00	cut
14 SIDE MIRROR RH	1 PC	\$90.00	cut
15 PETROL TANK BRACKET RH	1 PC	\$155.00	cut
16 TAIL LAMP LH	1 PC	\$65.00	cut
17 TAIL LAMP BRACKET LH	1 PC	\$45.00	cut
18 REAR NUMBER PLATE BRACKET	2PCS	\$140.00	mis
19 NUMBER PLATE LAMP	2PCS	\$110.00	mis
20 AIR CLEANER BOX	1 PC	\$290.00	cut
21 AIR FILTER	1 PC	\$145.00	cut
22 FRT SIGNAL LAMP RH	1 PC	\$130.00	cut
		\$4,080.00	
		\$408.00	\$4,488.00

Add 10%

3450
95
3545

Special Net			
23 REAR NUMBER PLATE	1 PC	\$35.00	mis
24 REAR REINFORCEMENT BAR	1 PC	\$950.00	bt - 750.
25 REAR REINFORCEMENT BAR BRACKET LH	1 PC	\$250.00	cut
26 REAR SIDE ALUMINIUM FRAME LH	1 PC	\$850.00	bt - 650.
27 REAR WOODEN PLANK SUPPORT	2PC	\$850.00	X 2 cm - 700X2
28 REAR WOODEN PLANK RUBBER SUPPORT LH	1 PC	\$180.00	cut
29 LH SIDE BOARD	1 PC	\$1,500.00	bt - 1200.
30 RH SIDE BOARD	1 PC	\$1,500.00	bt - 1200.
31 LH SIDE BOARD ALUMINIUM LOWER FRAME	1 PC	\$650.00	bt - 450.
32 RH SIDE BOARD ALUMINIUM LOWER FRAME	1 PC	\$650.00	bt - 450.
33 RH REINFORCEMENT BAR	1 PC	\$950.00	bt - 750.
34 ENGINE OIL	1 PC	\$150.00	cut
		\$9,365.00	

7065

FRT RH PILLAR ANTENNA - \$95 cut



友興汽車零件私人有限公司

YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708

TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858

Email: yewheng@yewhengauto.sg

Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S : SME MOTOR PTE LTD

KAKI BUKIT AVE 6 #02-15/16/17/18 AUTOBAY@KAKI
BUKIT BLK-D

SINGAPORE 417883

TEL: 67476106; FAX: 67442368; 64844303

NO: YLI1251004

PAGE: 1

DATE: 14/04/2021

A/C CODE: LYSME001


TERMS: 60 DAYS

P/O NO: YN5910X

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 8-98260593-1	RH DOOR	YDS	1	820.00	820.00 ✓
2 8-98037101-2	FRT OUTER HANDLE R	YDS	1	95.00	95.00 ✓
3 8-98039776-2	RH DOOR SIGNAL LAMP	YDS	1	115.00	115.00 ✓
4 8-98022774-4	STEP GARNISH RH	YDS	1	165.00	165.00 ✓
5 8-97405621-8	SIDE PANEL RH (WHITE)	YDS	1	240.00	240.00 ✓
6 99999	FRT RH CORNER PANEL SIDE RUBBER	YDS	1	75.00	75.00 ✓
7 8-98027552-2	RH SIDE MIRROR BRACKET TOP COVER(ROUND)	YDS	1	95.00	95.00 ✓
8 8-98241325-0	H/LAMP RH	YDS	1	350.00	350.00 ✓
9 8-98034056-1	H/LAMP LWR RUBBER	YDS	1	30.00	30.00 ✓
10 8-97406814-4	BUMPER FRT	YDS	1	400.00	400.00 ✓
11 8-98025211-4	BAR FRT BUMPER RH	YDS	1	150.00	150.00 ✓
12 8-98232058-1	FRT BUMPER FOG LAMP RH	YDS	1	280.00	280.00 ✓
13 8-94262542-3	SIDE MIRROR OUTSIDE	YDS	1	90.00	90.00 ✓
14 99999	PETROL TANK BRACKET RH	YDS	1	155.00	155.00 ✓
15 8-98034325-0	REAR LAMP LH	YDS	1	165.00	165.00 ✓
16 8-98329430-0	LAMP LICENSE PLATE	YDS	2	55.00	110.00 ✓
17 99999	NUMBER PLATE LAMP BRACKET	YDS	2	70.00	140.00 ✓
18 8-98155458-0	SIGNAL LAMP RH	YDS	1	130.00	130.00 ✓
19 8-97387265-3	ANTENNA	YDS	1	95.00	95.00 ✓

Print / KXM / 16/04/2021 10:44:56 AM

...Cont'd





友興汽車零件私人有限公司
YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130048W

TAX INVOICE

M/S : SME MOTOR PTE LTD

NO: YLI1251004
PAGE: 2

TOTAL QUANTITY:	21	TOTAL	SIN 3,700.00
		ADD GST @ 7%	259.00
		GRAND TOTAL	<u>SIN 3,959.00</u>

Print / KXM / 16/04/2021 10:44:56 AM

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

