LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Alfred Toh Date: 13 Apr 2021

Preliminary Advice

Insured Vehicle No : GBK9282L

TP Vehicle No : SMX7934D Accident Date : 12/03/2021 Make : TOYOTA PRIUS Assignment Date : 15/03/2021

Date of Inspection : 17/04/2021 Est. Duration of Repair : 8

Inspection At : TEAM AUTOPRO PTE LTD (SIN MING)

385 SIN MING DRIVE, #01-02 VICOM INSPECTION CENTRE

SINGAPORE 575718

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

(x) Other comments : survey on wp

Repairer's Estimate (Gross)	:S\$	18,898.80
Revised Amount	:S\$	8,108.05
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,108.05
Lump Sum Repair	:S\$	6,450.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.