

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motoricarzgarage@gmail.com

Register No.: 201919765N

ESTIMATION QUOTE

ZWR800401836

VEHICLE NO : SMP8482B

MAKE/MODEL : TOYOTA NOAH

DOA : 13/3/2021

CLAIM TYPE : THIRD PARTY CLAIM

Cecilia

No	Particular	Qty	Unit Price (S\$)	Amount (S\$)
	LIST ITEMS			1025
1	FRONT BUMPER <i>Disfold</i>	1	1,217.90	1,217.90 ✓
2	FRONT FENDER LH <i>Disfold</i>	1	987.90	788 987.90 ✓
3	FRONT DOOR LH <i>He m</i>	1	1,532.60	1,532.60 +
4	FOGLAMP LH <i>Canld</i>	1	360.00	360.00 ✓
5	FOGLAMP CHROME MOULDING <i>cut</i>	1	185.00	185.00 ✓
6	FRONT GRILLE ASSY <i>Canld</i>	1	1,718.90	798 1,718.90 ✓
7	BUMPER RETAINER LH <i>neu</i>	1	95.00	95.00 ✓
8	FRONT RIM LH <i>cut</i>	1	350.00	350.00 ✓
9	HEAD LAMP SUPPORT PANEL LH <i>Revised</i>	1	125.00	125.00 ✓
10	FRONT SENSOR <i>Disnd</i>	1	250.00	250.00 ✓
11	FRONT BUMPER CLIP <i>neu</i>	1	45.00	45.00 ✓
12	FRONT HEAD LAMP LH <i>Canld</i>	1	3,738.90	3291 3,738.90 ✓
13	FENDER INNER SHIELD LH <i>torn</i>	1	171.90	171.90 ✓
14	ABSOBER LH <i>Best</i>	1	472.30	472.30 ✓
15	LOWER ARM <i>Best</i>	1	1,202.30	579 1,202.30 ✓
16	STABILIZER <i>neu</i>	1	180.00	180.00 +
17	KNUCKLE ARM <i>Disnd</i>	1	663.40	565 663.40 ✓
18	WHEEL ALIGNMENT <i>neu</i>	2	50.00	100.00 50.00 ✓
19	REINFORCEMENT FORM <i>Foam Canld</i>	1	185.00	185.00 ✓
20	REINFORCEMENT <i>Best</i>	1	780.00	419 780.00 ✓
21	SUPPORT PANEL <i>Regis</i>	1	1,760.30	1,760.30 +
				16,071.40
	LESS 20%			(3,214.28)
	SUB TOTAL-LIST ITEMS			12,857.12
	SPECIAL NETT ITEMS			

9804.20

Regis len 25% : 7353.15

No	Particular	Qty	Unit Price (S\$)	Amount (S\$)
	SUB TOTAL- SPECIAL NETT ITEMS			-
	SUB TOTAL COST FOR PARTS			12,857.12
	<u>LABOUR</u>			
22	REMOVE ,REFIX FRONT SENSOR			50.00 ✓
23	PANEL BEATING,REMOVE,REPLACE ABOVE PARTS		1670	1,000.00 700
24	SPRAY PAINTING ACCIDENT AREA			1,000.00 700
25	REMOVE AND REFIX UNDERCARRIAGE			250.00 220
	SUB TOTAL-LABOUR			2,300.00
	GRAND TOTAL			15,157.12

Adrian L
L/S 16/03/21

06 Days

total: 9023.15
L/S: 7.2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: