



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

23/3/2021

Survey Details:

| | |
|---------------------|-----------------------------|
| Date of loss | 12-Mar-21 |
| Date of appointment | 15-Mar-21 |
| Date of survey | 16-Mar-21 |
| Location of survey | HIAP LEK AUTOMOBILE TRADING |

Vehicle Details:

| | |
|----------------------|---------------------------|
| Claim Type: | Third Party Claim |
| Vehicle number | SGD 5595M |
| Make and Model | MAZDA 6 4DR SEDAN 2.5L SP |
| Date of registration | 12/2/2015 |
| Excess | - |
| Market Value | \$ 57,000.00 |
| Parf Rebate | \$ 40,639.00 |
| Nett Loss | \$ 16,361.00 |

Repair details:

| | |
|------------------|------|
| Initial Estimate | \$ - |
|------------------|------|

Proposed/Revised repair cost:

| | |
|--------------------------------|------|
| Parts | |
| Check items (estimate) | |
| Labour | |
| Total | \$ - |
| Lump Sum(if applicable) | |

| | |
|----------------------------------|-----------------|
| Number of days for repair | <u>5</u> |
|----------------------------------|-----------------|



Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$4,500.00 - \$5,500.00.

Mandate:

| Liability(TP) | % | |
|-----------------------|----------------|-------------|
| Proposed repair cost | \$ | |
| Loss of use | \$ | no. of days |
| Loss of rental | \$ | no. of days |
| Loss of income | \$ | no. of days |
| LTA search fees | \$ | |
| Others | \$ | |
| Proposed Total | #VALUE! | |