

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796501 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57610
Date Estimated : 22/02/2021
Prepared By : Foong Shiuh Jye

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Loong Mun Soon
Apt Blk 510 Bukit Batok Street 52
#08-27
Singapore 650510

- ACCOUNT - 144674
ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ1186K	WBAJR12070CD80448	28/09/2020	5201	0

DESCRIPTION	VALUE
To replace front right door, and right side sill trim 1/2	1275 2,125.00
To spray paint front right door and right side sill trim	1539 1,711.00
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function. (1 door).	451 531.00
To check electrical wiring system at the front section for proper function including adjustment of headlights.	159 177.00
Sundries	nec 80.00

Total Labour 1: 4,624.00

DESCRIPTION	QTY	PRIC	VALUE
FRT RH DOOR ALUMINIUM	1	1,881.90	1,881.90
(S/L) DOOR WEATHERSTRIP	1	175.65	175.65
RH SILL TRIM PRIMED	1	425.55	425.55

Total Parts : 2,483.10

Plants hence notify
the following:
• To the insurance company after spray painting

Part(s) subject to confirmation
on a "Without Prejudice" basis
(s) is allowed
must be resurveyed and
val from Insurance Company

Steve CLKK) 16/3/21, 12:19pm
WLC RL

P/P

My BL sy
4 days

Labour 1	:	4,624.00
Parts	:	2,483.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	497.50
Grand Total	:	7,604.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **