

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Mar 2021

Preliminary Advice

Insured Vehicle No	: YQ1636Z		
TP Vehicle No	: GBJ8533A	Accident Date	: 10/03/2021
Make	: VOLVO C70	Assignment Date	: 16/03/2021
Date of Inspection	: 16/03/2021	Est. Duration of Repair	: 3
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,607.20
Revised Amount	:S\$	2,586.72
Check Items (Estimated)	:S\$	.00
Total	:S\$	2,586.72
Lump Sum Repair	:S\$	2,050.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on wp