Ref. No:



#### (SUPPLEMENTARY)

**INSURER: ECICS Limited (HQ)** 

**PARTICULARS OF CLAIM** 

Claim Type: OD (OWN DAMAGE)

Policy No: MPC20P00215300 Date of Loss: 10/03/2021

**SLV4491G** Vehicle Reg. No.: Driveable?

Driver Age/Info:

Party At Fault: **UNKNOWN** TP Injury Involved? Third Party Involved? YES NO

CHITRA DEVI D/O Insured/Claimant:

**KASIVISWANATHAN** 

Make/Model: SUBARU FORESTER, 2.0 I (A) Vehicle Reg. Date: 29/12/2017

Vehicle Colour: **BROWN** 

Engine No: FB20YB72715 Chassis No: JF1SJ5KC5JG101685

Odometer: 89442 KM

Paint Type:

Total Loss? NO Est. Duration of Repair 4

(day)

**Present Location:** BH AUTO SERVICES PTE LTD (SIN MING)

COST OF CLAIMS		Amount
Parts		440.00
Miscellaneous Items		0.00
Labour		0.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	440.00
	+ GST 7.00% (S\$)	30.80
	Nett Amount (S\$)	470.80
	+ Previous Estimates (S\$)	6,779.09
	Claim Total (S\$)	7,249.89

Generated using Merimen e-Claims Internet Estimation & Adjusting System

#### REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 May 2021)

Parts: M1-SUV SUBARU FORESTER 2.0 i (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: BH Auto Services Pte Ltd/SLV4491G/17/05/2021 14:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Estimates on Parts**

No. Qty Part No.	Particulars	%Disc	%Depr	Amount
1 1 F=Franchise part.	*Front Bumper buckled/cracked	0.00	0.00	*400.00 F
r-riandinse part.	Sub Total (S\$)		400.00	
+ Margin on L,N Items 10.00% (S\$)				40.00
	Total Parts (S\$)			440.00

BH Auto Services Pte Ltd/SLV4491G/17/05/2021 14:16. Not valid without Reference section. Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

#### **Estimates on Labour**

There are no labour items selected.

BH Auto Services Pte Ltd/SLV4491G/17/05/2021 14:16. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >