

TS

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 16 Mar 2021)

Parts: 192 **HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: ComfortDelGro Engineering Pte Ltd/SHA5383L/16/03/2021 08:13

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL de
2	1		*REAR BUMPER CTR MOULDING	20.00	0.00	*451.25 FL de
3	1		*REAR BUMPER LWR MOULDING	20.00	0.00	*155.00 FL RY
4	1		*REAR BUMPER BEAM	20.00	0.00	*394.80 FL R hy
5	2		*REAR BUMPER STAY RH/LH	20.00	0.00	*276.20 FL R hy
6	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL R Re
7	1		*REAR BUMPER REFLECTOR LH	20.00	0.00	*41.45 FL X hy
8	1		*REAR BUMPER FOGLAMP	20.00	0.00	*201.50 FL X hy
9	1		*REAR BUMPER TOW COVER	20.00	0.00	*98.80 FL X ut
10	1		*REAR BUMPER MAT	0.00	0.00	*50.00 F Re
11	1		*REVERSE SENSOR	0.00	0.00	*180.00 F X an
12	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F Re
13	1		*REAR NO.PLATE W/TRIM COVER	0.00	0.00	*55.00 F Re

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **2,585.40**
 - List Item Discount on L Items (S\$) **420.08**

Total Parts (S\$) **2,165.32**

ComfortDelGro Engineering Pte Ltd/SHA5383L/16/03/2021 08:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

932.65
 746.12.
 SN. 305

TS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00 ✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	400.00 350
2	SPRAY PAINTING	New	300.00 250
3	R/I REVERSE SENSOR	New	120.00 30
Gross Labour Cost (S\$)			820.00 630

ComfortDelGro Engineering Pte Ltd/SHA5383L/16/03/2021 08:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

\$1692.12.

-2 days

Tanjong 97495749

WP' 16/3/21 @ 4pm

p/p Resurvey after repair

02 days

Tanjong & Phang. Workable.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: