



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21003458/Kqd3e2	
			Date: 28/06/2021	
			Code: LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	GBH 5885P
	<b>Policy No.</b>	Z/20/VC00/107584	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	20/21/21/VC00/024325	<b>Excess (\$)</b>	1,000.00
	<b>Assign From</b>	GERALD POH	<b>Assign Date</b>	16/03/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	CITROEN BERLINGO (A)	<b>c.c</b>	1560
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	VF77FBHYMHJ754778	<b>Colour</b>	SILVER
	<b>Odometer</b>	110225 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	CONTINENTAL	7 mm
	<b>L/H Front Tyre</b>	195/65 R15	CONTINENTAL	7 mm
	<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	7 mm
	<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	12/03/2021	<b>Inspection Date</b>	17/03/2021
	<b>Survey held at</b>	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A) THE MARKET VALUE IS S\$54,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	