



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21003461/Kvf3n2 Date: 20/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 5874S		Veh. Inspected	SMQ 3018L
Policy No.			Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024331		Excess (\$)	0.00
Assign From	GERALD POH		Assign Date	17/03/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)		c.c	1597
Engine No.	HIDDEN		Year of Reg.	2019
Chassis No.	MRHFC5650KT001051		Colour	METALLIC BLUE
Odometer	14240 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		215/55 R16	HANKOOK	9 mm
L/H Front Tyre		215/55 R16	HANKOOK	9 mm
R/H Rear Tyre		215/55 R16	HANKOOK	9 mm
L/H Rear Tyre		215/55 R16	HANKOOK	9 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/03/2021		Inspection Date	22/03/2021
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	