

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0222/2021/GW
DATE	:	17-Mar-21
WIP	:	

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR SAMUEL JOHN WILLIAMS
ADDRESS	:	114 DEPOT ROAD #12-1031 SINGAPORE 100114
TELEPHONE	:	HP +65 81330109
TYPE OF CLAIM	:	THIRD PARTT CLAIMS
POLICY NO	:	P1021902R01
VEHICLE NO	:	SLR 1486 M
MODEL CODE	:	VW GOLF 1.4 TSI AT
MODEL YEAR	:	31/7/2017
ENGINE NO	:	CZC162240
CHASSIS NO	:	WVWZZZAUZHW120789
MILEAGE	:	
DATE IN	:	
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	12-Mar-21
PLACE OF ACCIDENT	:	CORPORATION ROAD BEFORE JALAN TUKANG



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLR 1486 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	S/N \$ 280.00	150 100
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	350
3	TO RESPRAY REAR BUMPER, RHS REAR FENDER AND REAR END PANELLING.	\$ 2,800.00	350
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	150 /
TOTAL LABOUR CHARGES		: \$ 4,672.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 1486 M

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER ✓ <i>DR</i>	1	\$	1,462.00	
2 REAR SENSOR BRACKET-LH/RH ✓ <i>MC</i>	2	\$	66.00	
3 REAR SENSOR BRACKET-LH/RH CENTER ✓ <i>MC</i>	2	\$	66.00	
4 2 PK PLASTIC ADHESIVE ✓ <i>MC</i>	1	\$	57.00	
5 BONDING AGENT ✓ <i>MC</i>	1	\$	60.00	
6 REAR BUMPER FIXING PARTS ✗	1	\$	97.00	
7 REAR BUMPER TOW COVER ?	1	\$	32.00	
8 REAR BUMPER SPOILER ?	1	\$	540.00	
9 REAR BUMPER GUIDE PROFILE-LH/RH ?	2	\$	130.00	
10 REAR REINFORCEMENT BEAM ?	1	\$	732.00	
11 REAR BUMPER SEURING STRIP ?	1	\$	112.00	
12 REAR BUMPER SENSOR SEAL RING ✓ <i>MC</i>	4	\$	14.00	
13 REAR LIGHT REFLECTOR LIGHT-LRH ?	1	\$	87.00	
14 TAILLIGHT OUTER-RH ✗	1	\$	358.00	
15 SUNDRIES ?	1	\$	250.00	
TOTAL SPARE PARTS	:	\$	3,813.00	
TOTAL LABOUR CHARGES	:	\$	4,672.00	
GRAND TOTAL	:	\$	8,485.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-17/02/21



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Steve (LKK)
17/3/21, 10.30am
3 days
P/P
Ry Bil Spry
W/L P/L

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT