



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21003470/Evd3e2 Date: 14/06/2021 Code: LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	Insured Veh.	Veh. Inspected	YP 4579R	
	Policy No. Z/20/VC00/108728	Coverage (\$)	0.00	
	Claim No. 20/21/21/VC00/024339	Excess (\$)	2,000.00	
	Assign From GERALD POH	Assign Date	16/03/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model HINO XZU710R	c.c	4009	
	Engine No. HIDDEN	Year of Reg.	2016	
	Chassis No. JHHUCS3H20K018779	Colour	WHITE	
	Odometer 84268 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	STANDARD ALLOY RIM	
	General FAIR			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	BRIDGESTONE	5 mm
	L/H Front Tyre	195 R15C	BRIDGESTONE	5 mm
	R/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm
	L/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date 15/03/2021	Inspection Date	17/03/2021	
	Survey held at MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
<b>5a. Remarks</b>				
	A) THE MARKET VALUE IS S\$55,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	