

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003478/UGA3Q2
Date: 17/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100506029
Claimant Vehicle No :	FBF7772D	Insured Vehicle No :	SKJ3607Y
Date of Loss:	20/12/2020	Nature of Claim:	TP
		Claim No:	8163358499SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBF7772D		
Make & Model:	HONDA CB150R, 149cc	Engine No:	CS150RE0007545
Reg. Date:	18/11/2011 (Man. Year: 2011)	Chassis No:	CS150R0007545
Colour:	Red	Odometer:	0 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,094.70	1,333.00	2,761.70	67.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	610.00	250.00	360.00	59.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,704.70	1,583.00	3,121.70	66.35
Approved Total (Overridden) (S\$)		1,200.00		

Nett Amount (S\$)	4,704.70	1,200.00	3,504.70	74.49
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 17/03/2021

Date Inspected: 18/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
1 KAKI BUKIT AVE 6 #02-62
Singapore 417883

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Repair	175.00 FL	*- FL
2	2		*FORK INNER TUBES	Not Necessary	370.00 FL	*- FL
3	1		*WINDSHIELD	Not Necessary	90.00 FL	*- FL
4	1		*SIDE MIRROR (O/S)	Cut	60.00 FL	*60.00 FL
5	1		*HANDLE BAR	Bent	115.00 FL	*115.00 FL
6	1		*HANDLE BAR END	Missing	45.00 FL	*30.00 FL
7	1		*SET HAND GRIP	Torn	50.00 FL	*50.00 FL
8	1		*FRONT SIGNALS	O/S Broken	340.00 FL	*80.00 FL
9	1		*BRAKE LEVER (O/S)	Scratched	65.00 FL	*65.00 FL
10	1		*METER COVER	Cut	150.00 FL	*150.00 FL
11	1		*SIDE FAIRING -R/H	Cracked	320.00 FL	*320.00 FL
12	1		*SIDE INNER FAIRING -R/H	Cracked	220.00 FL	*185.00 FL
13	1		*LOWER FAIRING	Cracked	120.00 FL	*120.00 FL
14	1		*FRONT FOOTREST-R/H	Torn	45.00 FL	*45.00 FL
15	1		*FRONT FOOTREST BRACKET-R/H	Serviceable	75.00 FL	*- FL
16	1		*REAR FOOTREST -R/H	Serviceable	45.00 FL	*- FL
17	1		*BRAKE PEDAL	Serviceable	58.00 FL	*- FL
18	1		*EXHAUST ASSY	Repair	800.00 FL	*- FL
19	1		*EXHAUST COVER	Dented	150.00 FL	*150.00 FL
20	1		*REAR FAIRING -R/H	Repair	180.00 FL	*- FL
21	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
22	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
23	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
24	1		*SET STEERING CONE	Not Necessary	95.00 FS	*- FS
25	1		*SET STICKER	Necessary	120.00 FS	*100.00 FS
26	1		*REAR BOX	Serviceable	490.00 FS	*- FS
27	1		*REAR BOX BRACKET	Serviceable	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,442.00	1,470.00
- List Item Discount on L Items 10.00/10.00% (\$)	347.30	137.00
Total Parts (\$)	4,094.70	1,333.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	480.00	250.00
Gross Labour Cost (\$\$)			610.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >