



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:TAN JUN HONG			Ref: CC4/ASM21003481/Uga3q2 Date: 18/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8573A	Veh. Inspected	FBC 7662D	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M0353B	Excess (\$)	0.00	
Assign From		Assign Date	17/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	BAJAJ PULSAR DTS-I 180	c.c	179	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MD2DHDJZZPCJ69112	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90-80-17	MICHELIN	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120-70-17	MICHELIN	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT N/S PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/03/2021	Inspection Date	18/03/2021	
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	